

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010900/REA3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100382516
Claimant Vehicle No :	SHC6891U	Insured Vehicle No :	SKJ138D
Date of Loss:	23/10/2021	Nature of Claim:	TP
		Claim No:	2798195220SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6891U	Engine No:	D4FDEH313408
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5623063
Reg. Date:	30/09/2015 (Man. Year: 2015)	Odometer:	529304 km
Colour:	Grey		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,154.70	2,643.10	1,511.60	36.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,100.00	920.00	45.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,174.70	3,743.10	2,431.60	39.38
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	6,174.70	3,000.00	3,174.70	51.41
+ GST 7.00/7.00% (S\$)	432.23	210.00	222.23	51.41
Nett Amount (S\$)	6,606.93	3,210.00	3,396.93	51.41
+ Loss of Use (6.0 x S\$40.00/day) (S\$)		240.00		
+ Car Rental (6.0 x S\$67.41/day) (S\$)		404.46		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,856.46		
Global Sum Settlement (S\$)		3,850.00		

INSPECTION

Date of Assignment:	25/10/2021	
Date Inspected:	25/10/2021	Inspected At: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S HEAD LAMP	Cracked	1,028.00 FL	*1,028.00 FL
2	1		*BONNET GRILLE	Not Necessary	385.00 FL	*- FL
3	1		*FRONT BUMPER	Cracked	531.00 FL	*531.00 FL
4	1		*FRONT BUMPER EMBLEM	Not Necessary	44.00 FL	*- FL
5	2		*REAR BUMPER N/S & O/S SIDE RETAINER	Not Necessary	32.00 FL	*- FL
6	1		*FRONT BUMPER N/S UPPER BRACKET	Not Necessary	16.00 FL	*- FL
7	1		*FRONT BUMPER N/S SUPPOT BRACKET	Not Necessary	16.00 FL	*- FL
8	1		*FRONT BUMPER N/S PROTECTOR	Not Necessary	51.00 FL	*- FL
9	1		*FRONT BUMPER N/S FOG LIGHT COVER	Not Necessary	66.00 FL	*- FL
10	1		*FRONT DOOR LH(NPA)	Not Necessary	0.00 FL	*- FL
11	1		*N/S DOOR MIRROR	Not Necessary	590.00 FL	*- FL
12	1		*FRNT N/S WHEEL COVER	Cracked	116.00 FL	*116.00 FL
13	1		*FRONT N/S FENDER	Repair	384.00 FL	*- FL
14	1		*FRONT N/S FENDER INNER SHIELD	Scratched	120.00 FL	*120.00 FL
15	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
16	1		*FRONT N/S FENDER STICKER	Not Necessary	30.00 FS	*- FS
17	1		*SET FRONT N/S FENDER INNER SHIELD CLIPS	Necessary	28.00 FS	*20.00 FS
18	1		*SUNDRY	Necessary	50.00 FS	*20.00 FS
19	2		*FRONT N/S & O/S SHOCK ABSORBER	Bent	660.00 FL	*660.00 FL
20	1		*FRONT N/S STABILIZER LINK	Bent	86.00 FL	*86.00 FL
21	1		*FRONT N/S ENGINE UNDER COVER	Cracked	174.00 FL	*174.00 FL
22	1		*FRONT O/S ENGINE UNDER COVER	Cracked	144.00 FL	*144.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,599.00	2,929.00
- List Item Discount on L Items 10.00/10.00% (S\$)	444.30	285.90
Total Parts (S\$)	4,154.70	2,643.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE AND REPLACE THE FRONT N/S UNDERCARRIAGE	New	150.00	80.00
2	TO DISMANTLE AND REPLACE THE FRONT O/S UNDERCARRIAGE	New	150.00	80.00
3	TO FOCUS AND ADJUST FRONT N/S & O/S HEAD LAMPS	New	60.00	30.00
4	TOWING FEE	New	50.00	50.00
5	TO CHECK FRONT WHEEL ALIGNMENT	New	80.00	60.00
6	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME ,ETC	New	650.00	400.00
7	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER ,FRONT DOOR LH ,SIDE MIRROR LH	New	800.00	400.00
8	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
Gross Labour Cost (\$\$)			2,020.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >