

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010901/R1PA3Q2
Date: 17/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210005790
Claimant Vehicle No :	SHA1145J	Insured Vehicle No :	EZ20X
Date of Loss:	22/10/2021	Nature of Claim:	TP
		Claim No:	3828957393SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1145J	Engine No:	G4LEKU421511
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU192900
Reg. Date:	30/03/2021 (Man. Year: 2019)	Odometer:	55754 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	889.76	746.12	143.64	16.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	890.00	230.00	20.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,009.76	1,636.12	373.64	18.59
+ GST 7.00/7.00% (S\$)	140.68	114.53	26.15	18.59

Nett Amount (S\$)	2,150.44	1,750.65	399.79	18.59
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,453.41		
Global Sum Settlement (S\$)		2,450.00		

INSPECTION

Date of Assignment:	25/10/2021		
Date Inspected:	25/10/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL	
2	1		*REAR BUMPER REFLECTOR RH	Not Necessary	41.45 FL	*- FL	
3	1		*REAR BUMPER CENTRE MOULDING -BLACK	Scratched	451.25 FL	*451.25 FL	
4	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	138.10 FL	*- FL	
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL	
					Sub Total (\$)	1,112.20	932.65
					- List Item Discount on L Items 20.00/20.00% (\$)	222.44	186.53
					Total Parts (\$)	889.76	746.12

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE -REAR FENDER RH	New	600.00	500.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
			Gross Labour Cost (\$\$)	890.00
			1,120.00	

Report was unsubmitted during this print-out.

< END OF ESTIMATES >