

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010902/KGA3Q2**Date:** 16/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900171483
Claimant Vehicle No :	SNB6293E	Insured Vehicle No :	SDS989A
Date of Loss:	21/10/2021	Nature of Claim:	TP
		Claim No:	0259861431SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB6293E	Engine No:	2NR1224859
Make & Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID CVT (A)	Chassis No:	NRE1610094849
Reg. Date:	01/09/2021 (Man. Year: 2021)	Odometer:	6997 km
Colour:	Metallic Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,938.14	1,246.04	5,692.10	82.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,255.00	1,625.00	56.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,818.14	2,501.04	7,317.10	74.53
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	9,818.14	2,000.00	7,818.14	79.63
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,207.45		

INSPECTION

Date of Assignment:	25/10/2021	
Date Inspected:	25/10/2021	Inspected At: Lian Hong Seng Motor Works - Ang Mo Kio (HQ) BLK 5035 ANG MO KIO IND.PARK 2 #01-345 Singapore 569537
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	798.50 FL	*- FL
2	10		*FRONT BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
3	1		*LH FRONT BUMPER RETAINER	Serviceable	67.50 FL	*- FL
4	1		*LH FRONT BUMPER SIDE BRACKET	Serviceable	78.50 FL	*- FL
5	1		*LH HEADLAMP	Serviceable	1,324.30 FL	*- FL
6	1		*LH HEADLAMP CHROME MOULDING	Serviceable	189.50 FL	*- FL
7	1		*LH FOGLAMP COVER	Serviceable	186.40 FL	*- FL
8	1		*LH FRONT FENDER	Bent	465.30 FL	*465.30 FL
9	1		*LH FRONT FENDER INNER SHIELD	Serviceable	187.50 FL	*- FL
10	10		*LH FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FL	*- FL
11	1		*LH FRONT ABSORBER	Serviceable	356.40 FL	*- FL
12	1		*LH FRONT KNUCKLE ARM	Bent	355.70 FL	*355.70 FL
13	1		*LH FRONT LOWER ARM	Distorted	324.30 FL	*324.30 FL
14	1		*LH FRONT LOWER ARM BALL JOINT	Serviceable	198.60 FL	*- FL
15	1		*LH FRONT WHEEL HUB W BEARING	Bent / Necessary	387.69 FL	*387.69 FL
16	1		*LH FRONT RIM	Dented / Cut	764.40 FL	*128.40 FL
17	1		*LH WING MIRROR	Serviceable	875.30 FL	*- FL
18	1		*LH FRONT DOOR	Repair	1,109.30 FL	*- FL
19	1		*LH FRONT DOOR BLACK TAPE	Not Necessary	145.30 FL	*- FL
20	1		*LH FRONT DOOR GLASS REGULATOR W MOTOR	Serviceable	325.40 FL	*- FL
21	1		*LH FRONT DOOR ACTUATOR	Serviceable	344.30 FL	*- FL
22	1		*LH FRONT TYRE	Serviceable	450.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					9,084.19	1,661.39
- List Item Discount on L Items 25.00/25.00% (S\$)					2,146.05	415.35
Total Parts (S\$)					6,938.14	1,246.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FACILITATE REPAIR	New	1,000.00	350.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	600.00
3	TO REMOVE AND REFIT LH FRONT DOOR COMPONENT	New	150.00	0.00
4	TO REMOVE AND REFIT LH FRONT UNDERCARRIAGE	New	350.00	180.00
5	WHEEL ALIGNMENT	New	150.00	60.00
6	TO ROTATE AND BALANCING LH FRONT WHEEL	New	100.00	20.00
7	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	50.00	15.00
8	RUST PROOFING	New	80.00	30.00
Gross Labour Cost (\$)			2,880.00	1,255.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >