

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	MS FIRST CAPITA	L INSURANCE LTD		Ref:	CS3/FCI21010910/Gtf3e2	
	36 ROBINSON RO SINGAPORE 0688		Date:	03/11/2021		
				Code:	FCI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBB 2198R	Veh. Inspected	ł	SKE 8014B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D21002975MFCV	Excess (\$)		0.00	
	Assign From	RACHELWU LIMEI	Assign Date		25/10/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 520I 2.0L	c.c		1997	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	WBAXG12040DW36181	Colour		BLACK	
	Odometer	136844 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/55 R17	PIRELLI		6 mm	
	L/H Front Tyre	225/55 R17	PIRELLI		6 mm	
	R/H Rear Tyre	225/55 R17	PIRELLI		6 mm	
	L/H Rear Tyre	225/55 R17	PIRELLI		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUS	CLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	. General Information					
	Accident Date	23/10/2021	Inspect Date /	Time	26/10/2021 (02:00 PM)	
	Survey held at	eld at SHENG LI LAI				
	2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921					
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$34,000.00					

Report Ref No. CS3/FCI21010910/Gtf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser