



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 4474B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	NOT NECESSARY	557.00	-
1	REAR BOOTLID LOCK STRIKER	NOT NECESSARY	28.00	-
1	REAR BOOTLID MECHANISM LOCK	NOT NECESSARY	58.00	-
2	REAR TAILLAMP L/R	NOT NECESSARY	508.00	-
2	REAR FENDER INNER SHIELD L/R	NOT NECESSARY	64.00	-
1	REAR BUMPER	CRACKED	731.00	731.00
1	REAR BUMPER CENTER BEAM	NOT NECESSARY	68.00	-
2	REAR BUMPER REFLECTOR L/R	NECESSARY	40.00	40.00
1	REAR BUMPER REINFORCEMENT	BENT	169.00	169.00
2	REAR BUMPER SIDE RETAINER L/R	BENT	40.00	40.00
1	REAR BUMPER TOW COVER	NECESSARY	20.00	20.00
1	REAR END PANEL INNER TOP GARNISH	CRACKED	140.00	140.00
4	REAR END PANEL INNER TOP GARNISH CLIPS	NECESSARY	26.00	15.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	407.00	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	359.00	-
	LESS 10% DISCOUNT		-321.50	-115.50
			2,893.50	1,039.50
<u>SPECIAL NETT ITEMS</u>				
2	SET REAR FENDER INNER SHIELD CLIPS L/R (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	CRACKED	350.00	200.00
1	REAR BUMPER NUMBER PLATE (SN)	BENT	25.00	20.00
1	REAR BUMPER NUMBER PLATE HOLDER (SN)	CRACKED	50.00	30.00
			515.00	280.00
<u>LABOUR</u>				
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		120.00	30.00
	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET.		80.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	400.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,000.00	400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	30.00
			2,300.00	890.00
GRAND TOTAL			5,708.50	2,209.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,750.00

Report Ref No. CS3/SMR21007103/Euf3e2-1

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.