



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 2177D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP RH	CRACKED	3,369.80	3,209.00
1	SET HEADLAMP CLIPS	NOT NECESSARY	30.00	-
1	FRONT BUMPER	TORN	1,245.30	1,151.00
1	FRONT BUMPER SIDE RETAINERS	NOT NECESSARY	68.90	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	30.00
1	FRONT BUMPER TOP PAD	NOT NECESSARY	492.50	-
1	FRONT BUMPER TOP GARNISH	NOT NECESSARY	158.30	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	552.30	-
1	FRONT BUMPER SPONGE	CRACKED	185.90	185.90
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	138.50	-
1	FRONT BUMPER ENGINE UNDERCOVER	NOT NECESSARY	158.30	-
1	FRONT BUMPER LOWER REINFORCEMENT	NOT NECESSARY	98.50	-
1	FRONT BUMPER FOG LAMP RH	NOT NECESSARY	701.00	-
1	FRONT BUMPER FIG LAMP BRACKET RH	NOT NECESSARY	56.00	-
1	FRONT BUMPER FOG LAMP COVER RH	NOT NECESSARY	59.60	-
1	FRONT BUMPER FOG LAMP COVER CHROME RH	NOT NECESSARY	108.20	-
2	FRONT PARKING SENSORS RH @\$285.60	NOT NECESSARY	571.20	-
2	FRONT PARKING SENSOR HOLDERS RH @\$45.20	NOT NECESSARY	90.40	-
1	FRONT GRILLE	CRACKED	648.00	517.00
1	FRONT GRILLE BADGE	NECESSARY	58.20	58.20
1	FRONT GRILLE CENTRE BRACKET	NOT NECESSARY	98.30	-
2	FRONT GRILLE OUTER CHROME MOULDING @\$176.30	NOT NECESSARY	352.60	-
1	SET FRONT GRILLE CLIP	NOT NECESSARY	30.00	-
2	FRONT LOWER GRILLE SIDE BRACKET @\$85.90	NOT NECESSARY	171.80	-
1	FRONT FENDER INNER SHIELD RH	NOT NECESSARY	145.30	-
1	FRONT FENDER RH	NOT NECESSARY	398.50	-
1	SET FRONT FENDER INNER SHIELD CLIPS	NOT NECESSARY	30.00	-
1	FRONT BONNET	DENTED	1,268.50	1,268.50
1	FRONT BONNET LOCK	NOT NECESSARY	186.50	-
2	FRONT BONNET HINGES @\$65.20	NOT NECESSARY	130.40	-
1	FRONT BONNET INNER SEAL	NOT NECESSARY	108.50	-

Report Ref No. CS/UOI21010912/Aqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SUPPORT PANEL	NOT NECESSARY	578.30	-
	LESS 20% DISCOUNT		-2,467.92	-1,283.92
			9,871.68	5,135.68
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE WITH COVER (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING.		1,200.00	400.00
	SPRAY PAINTING.		1,200.00	400.00
	CHECK WIRING ON HEADLAMP.		120.00	30.00
	TO REMOVE / TOP UP GAS.	NOT NECESSARY	120.00	-
	ANTI RUST.	NOT NECESSARY	100.00	-
	REMOVE AND INSTALL FRONT SENSOR.		120.00	50.00
			2,860.00	880.00
	GRAND TOTAL		12,781.68	6,015.68

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,800.00
---	--	--	--	-----------------

Report Ref No. CS/UOI21010912/Aqf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.