

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21010914/R1TY3E2

**Date:** 23/11/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00109102001		
<b>Claimant Vehicle No :</b>	SLP7493M	<b>Insured Vehicle No :</b>	GBF4779E		
Date of Loss:	22/10/2021	Nature of Claim:	TP	Claim No:	SNM21D206066/C02/TANCHC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7493M	Engine No:	CZC161542
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A)	Chassis No:	WVWZZZAUZHW119666
Reg. Date:	16/06/2017 (Man. Year: 2016)	Odometer:	61425 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,427.43	3,630.71	2,796.72	43.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,210.00	4,880.00	5,330.00	52.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,637.43</b>	<b>8,510.71</b>	<b>8,126.72</b>	<b>48.85</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,164.62</b>	<b>595.75</b>	<b>568.87</b>	<b>48.85</b>
<b>Nett Amount (S\$)</b>	<b>17,802.05</b>	<b>9,106.46</b>	<b>8,695.59</b>	<b>48.85</b>

### INSPECTION

Date of Assignment:	25/10/2021		
Date Inspected:	27/10/2021	Inspected At:	Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	5.0 days		

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2021)
<b>Parts:</b>	144	VOLKSWAGEN GOLF 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLP7493M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,317.70 FS	*1,317.70 FS
2	1		*SUPPORT PART RHS BUMPER INNER BRACKET	Serviceable	59.30 FS	*- FS
3	1		*GUIDE PIECE RHS BUMPER SIDE BRACKET	Necessary	22.85 FS	*22.85 FS
4	1		*SENSOR BRACKET	Necessary	15.02 FS	*15.02 FS
5	1		*SENSOR BRACKET	Necessary	15.02 FS	*15.02 FS
6	2		*SENSOR BRACKET	Necessary	30.04 FS	*30.04 FS
7	1		*2K-PLASTIC ADHESIVE	Necessary	81.39 FS	*81.39 FS
8	1		*BODING AGENT FOR PLASTIC	Necessary	65.42 FS	*65.42 FS
9	1		*TWIN HALOGEN HEADLAMPS RHS H/LAMP	Serviceable	766.75 FS	*- FS
10	1		*FLAT CONTACT HOUSING H/LAMP WIRE HOUSING	Serviceable	21.17 FS	*- FS
11	1		*FENDER	Torn	631.36 FS	*631.36 FS
12	1		*CROSS SUPPORT RHS FENDER BRACKET	Necessary	34.34 FS	*34.34 FS
13	4		*RIVETTED CAP NUT	Necessary	10.00 FS	*10.00 FS
14	1		*WHEELHOUSE LINER RHS FENDER LINER (UPPER)	Serviceable	188.98 FS	*- FS
15	1		*REAR VIEW MIRROR HOUSING RHS MIRROR HOUSING	Cut	597.87 FS	*597.87 FS
16	1		*MIRROR CAP PRIMED RHS MIRROR COVER	Cut	180.60 FS	*180.60 FS
17	1		*MIRROR GLASS	Serviceable	197.66 FS	*- FS
18	1		*SIDE WINDOW RHS A-PILLAR GLASS	Necessary	131.89 FS	*131.89 FS
19	1		*1K WINDOW ADHESIVE	Necessary	51.30 FS	*51.30 FS
20	1		*ADHESIVE REMOVER	Necessary	119.97 FS	*119.97 FS
21	1		*PRIMER	Necessary	28.52 FS	*28.52 FS
22	1		*ACTIVATOR FOR PRECOATED W	Necessary	26.23 FS	*26.23 FS
23	2		*APPLICATOR	Necessary	20.94 FS	*20.94 FS
24	1		*GLASS CHANNEL BLACK RHS FRT DOOR CHANNEL SEAL	Cut	250.25 FS	*250.25 FS
25	1		*TRIM FOR DOOR WINDOW FRAM RHS REAR DOOR SIDE TRIM (BLACK) (NOT NECESSARY)	Not Consistent With The Impact	97.89 FS	*- FS
26	1		*ALLOY WHEEL ALUMINIUM SHI	Not Necessary	1,461.36 FS	*- FS
27	1		*RUBBER VALVE	Not Necessary	3.61 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** 6,427.43 3,630.71

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	B&P WHEEL ALIGNMENT	New	360.00	0.00
4	R&R RIM & BALANCE	New	50.00	0.00
5	LABOUR	New	3,360.00	1,680.00
6	SPRAY PAINTING	New	4,000.00	1,600.00
7	R&R RHS MIRROR HOUSING	New	840.00	420.00
8	R&R RHS A-PILLAR GLASS	New	840.00	420.00
<b>Gross Labour Cost (\$)</b>			<b>10,210.00</b>	<b>4,880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >