

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010927/BEA3Q2**Date:** 18/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100411171-06
Claimant Vehicle No :	SMA4422E	Insured Vehicle No :	SKS6548S
Date of Loss:	24/10/2021	Nature of Claim:	TP
		Claim No:	6892321264SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA4422E		
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Engine No:	2ZR0B46889
Reg. Date:	08/06/2018 (Man. Year: 2018)	Chassis No:	ZVW400029163
Colour:	Black	Odometer:	332635 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,826.23	14,091.40	13,734.83	49.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,480.00	3,360.00	3,120.00	48.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,306.23	17,451.40	16,854.83	49.13
Approved Total (Overridden) (S\$)		13,950.00		
(S\$)	34,306.23	13,950.00	20,356.23	59.34
+ GST 7.00/7.00% (S\$)	2,401.44	976.50	1,424.94	59.34
Nett Amount (S\$)	36,707.67	14,926.50	21,781.17	59.34
+ Loss of Use (20.0 x S\$80.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		64.20		
Nett Liability (S\$)		16,598.15		
Global Sum Settlement (S\$)		16,590.00		

INSPECTION

Date of Assignment: 25/10/2021

Date Inspected: 26/10/2021 Inspected At:

Estimated Period of Repair: 14.0 days

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING
 AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,120.00 FL	*988.30 FL
2	1		*BONNET INNER LOCK	Jammed	158.00 FL	*127.50 FL
3	1		*BONNET HINGE (RH)	Bent	84.00 FL	*59.90 FL
4	1		*FRONT BUMPER	Broken	886.90 FL	*781.00 FL
5	1		*FRONT BUMPER LOGO	Necessary	185.00 FL	*88.00 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	284.00 FL	*124.80 FL
7	1		*FRONT BUMPER INNER SPONGE	Broken	358.20 FL	*120.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	684.30 FL	*- FL
9	1		*FRONT BUMPER UPPER GRILLE	Broken	189.70 FL	*189.70 FL
10	1		*FRONT BUMPER LOWER GRILLE	Broken	486.20 FL	*486.20 FL
11	1		*FRONT BUMPER DAY LIGHT RH	Broken	287.60 FL	*287.60 FL
12	1		*FRONT BUMPER SIDE AIR DUCT RH	Missing	87.60 FL	*87.60 FL
13	1		*FRONT BUMPER FOG LAMP RH	Not Damaged	385.60 FL	*- FL
14	1		*FRONT BUMPER FOG LAMP GARNISH RH	No such part	440.00 FL	*- FL
15	1		*FRONT SUPPORT PANEL	Not Damaged	1,248.60 FL	*- FL
16	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Damaged	158.00 FL	*- FL
17	2		*HEADLAMP	Broken	5,796.00 FL	*3,914.40 FL
18	2		*HEADLAMP LOWER BRACKET	Broken	364.60 FL	*160.00 FL
19	1		*HEADLAMP PANEL RH	Dented	188.50 FL	*89.20 FL
20	1		*FRONT FENDER RH	Dented	1,233.00 FL	*850.00 FL
21	1		*FRONT FENDER INNER COWLING RH	Broken	187.60 FL	*187.60 FL
22	1		*FRONT FENDER INNER COWLING BRACKET RH	Broken	68.30 FL	*68.30 FL
23	1		*FRONT FENDER EMBLEM HYBRID	Necessary	108.00 FL	*80.00 FL
24	1		*FRONT FENDER SIDE GLASS MOULDING	Not Damaged	289.50 FL	*- FL
25	1		*FRONT WHEEL HOUSE PANEL RH	Not Damaged	992.00 FL	*- FL
26	1		*FRONT DOOR RH	Dented	1,450.00 FL	*1,103.00 FL
27	1		*FRONT DOOR BLACK TAPE	Necessary	115.00 FL	*60.00 FL
28	1		*FRONT DOOR INNER LOCK	Jammed	489.00 FL	*153.60 FL
29	1		*FRONT DOOR LOCK STRIKER	Not Damaged	86.50 FL	*- FL
30	1		*FRONT DOOR OUTER HANDLE	Dented	482.60 FL	*143.60 FL
31	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	214.60 FL	*- FL
32	1		*FRONT DOOR REGULATOR	Bent	451.00 FL	*451.00 FL
33	1		*FRONT DOOR REGULATOR MOTOR	Not Damaged	385.60 FL	*- FL
34	1		*FRONT DOOR GLASS CHANNEL	No such part	445.70 FL	*- FL
35	1		*FRONT DOOR TRIMBOARD	Broken	496.90 FL	*496.90 FL
36	1		*FRONT DOOR FRAME RUBBER	Torn	106.90 FL	*106.90 FL
37	2		*FRONT DOOR HINGE	Bent	168.00 FL	*168.00 FL
38	1		*FRONT DOOR PILLAR RH	Dented	1,185.60 FL	*852.50 FL
39	1		*FRONT WINDSCREEN MOULDING	Necessary	288.70 FL	*123.50 FL
40	1		*FRONT SIDE MIRROR RH	Broken	876.90 FL	*876.90 FL
41	1		*SIDE SKIRT RH	Broken	655.30 FL	*379.60 FL
42	1		*REAR DOOR RH	Repair	1,430.00 FL	*- FL
43	1		*FRONT WIPER GARNISH	Not Damaged	386.90 FL	*- FL
44	1		*FRONT WIPER WASHER TANK	Broken	410.60 FL	*230.00 FL
45	1		*FRONT WIPER WASHER TANK MOTOR	Scratched	287.90 FL	*185.00 FL
46	1		*FRONT LOWER ARM RH	Bent	451.20 FL	*412.00 FL
47	1		*FRONT KNUCKLE AMR RH	Dented	453.00 FL	*360.70 FL
48	1		*FRONT KNUCKLE AMR BEARING RH	Jammed	487.00 FL	*223.40 FL
49	1		*FRONT SHOCK ABSORBER RH	Bent	422.80 FL	*422.80 FL
50	1		*FRONT LINKAGE RH	Not Damaged	214.00 FL	*- FL
51	1		*FRONT ABS SENSOR RH	Not Damaged	198.54 FL	*- FL
52	1		*FRONT CROSSMEMBER	Bent	1,668.20 FL	*875.00 FL
53	1		*STEERING RACK	Bent	1,882.00 FL	*1,620.70 FL
54	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
55	1		*BONNET SEALANT	Necessary	100.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
57	1		*FRONT BUMPER UPPER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
58	1		*FRONT BUMPER LOWER GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
59	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
60	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
61	1		*FRONT FENDER SEALANT	Necessary	100.00 FS	*30.00 FS
62	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
63	1		*FRONT FENDER SIDE GLASS SEALANT	Not Necessary	100.00 FS	*- FS
64	1		*FRONT FENDER SIDE GLASS CLIPS	Not Necessary	50.00 FS	*- FS
65	1		*FRONT FENDER SIDE GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
66	1		*FRONT WHEEL HOUSE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
67	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*40.00 FS
68	1		*FRONT DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
69	1		*FRONT DOOR PILLAR SEALANT	Necessary	100.00 FS	*20.00 FS
70	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*30.00 FS
71	1		*FRONT WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
72	1		*FRONT WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
73	1		*SIDE SKIRT CLIPS	Necessary	50.00 FS	*30.00 FS
74	1		*RADIATOR COLANT	Not Necessary	80.00 FS	*- FS
75	1		*A/C FLIUD	Not Necessary	80.00 FS	*- FS
76	1		*FRONT ALLOY RIM	Not Necessary	980.00 FS	*- FS
77	1		*FRONT ALLOY RIM CAP	Cut	380.00 FS	*80.00 FS
78	1		*FRONT TYRE	Cut	480.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	35,941.64	18,575.20
- List Item Discount on L Items 25.00/25.00% (S\$)	8,115.41	4,483.80
Total Parts (S\$)	27,826.23	14,091.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R BONNET COMPONENT	New	150.00	0.00
2	R&R RADIATOR	New	150.00	0.00
3	R&R A/C CONDENSER	New	150.00	0.00
4	R&R HYBRID COOLER	New	150.00	0.00
5	R&R FRONT FENDER SIDE GLASS	New	250.00	40.00
6	R&R FRONT DOOR COMPONENT	New	150.00	80.00
7	R&R FRONT WINDSCREEN	New	250.00	120.00
8	R&R FRONT UNDER CARRIAGE	New	300.00	150.00
9	R&R FRONT TYRE AND BALANCING	New	100.00	30.00
10	R&R STEERING RACK	New	150.00	80.00
11	WHEEL ALIGNMENT	New	180.00	60.00
12	UPHOLSTERY	New	200.00	0.00
13	CHECK WIRING	New	100.00	0.00
14	PANEL BEATING	New	2,000.00	1,600.00
15	RUST PROOFING	New	200.00	0.00
16	SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (S\$)			6,480.00	3,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >