

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Our reference:

20-05-9261

Date:

9/6/2020

c/o Team Autopro Pte Ltd 385 Sin Ming Drive #01-02 Vicom Inspection Centre Singapore 575718

**Dear Sirs** 

RE:

Road Traffic Accident on 14/3/2020

Tan Lay Bee

In accordance with your instructions received in this office on

26/5/2020

, we made arrangements to

examine the vehicle on

26/5/2020

at above-mentioned address. The following data was

recorded:

#### Vehicle details

Make	Volkswagen	Registration	SKD8647E
Model	Passat	Chassis	WVWZZZ3CZCE540247
Colour	Black	Gearbox	Auto
Odometer	99611km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

#### Tyre Depths

Front left	235/45R17	85% Pirelli		
Front right	235/45R17	85% Pirelli		
Rear left	235/45R17	85% Pirelli		
Rear right	235/45R17	85% Pirelli		

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

#### Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$6,700.00 and 6 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

## Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
  Impact Analysis Academy Pte Ltd
  IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171** 

Our reference

20-05-9261

Date

9/6/2020

Page

2

# **Section A: Damaged Parts Assessment**

Part's Description	ত্য়েy	Condition As ,, inspected	Repairer's Estimate	Our Adjustment "
<u>List Items:</u>				
Boot lid	1	damaged	3250.00	3250.00
Rear fender rh	1	damaged	2850.00	2850.00
Rear windscreen glass moulding	1	necessary	285.50	285.50
Boot lid logo	1	necessary	112.00	112.00
Boot lid emblem TBI	1	necessary	63.50	63.50
Boot lid emblem PASSAT CC	1	necessary _	115.80	115.80
	Sub- Total (	cost	6676.80	6676.80
	Percentage discount :	10%	667.68	667.68
	Sub-Total costs j	for parts	6009.12	6009.12
Special Nett Items:				
Rear windscreen sealant	1	necessary	50.00	50.00
Near Windowsell Scalaric	Sub-Total costs j	· =	50.00	50.00
	Sub-rotur costs j	=	30.00	50.00
<b>විසැප</b> ම්ලාක්ව				
*	*	*	0.00	0.00
	Sub- Total o	osts	0.00	0.00
	Total costs for	parts _	6059.12	6059.12
		_		

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
   Infoknights International Services (Philippines)
   IABN Pte Ltd www.iaconsultingsg.com



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

20-05-9261

Date

9/6/2020

Page

3

## **Section B: Labour Cost Calculation**

		Total la	bour cost	\$ 1,875.00
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$	50.00	0.5	\$ 25.00
Remove and refix rear windscreen glass & inner trim to facilitate the replacment of rear fender. (2-man job)	\$	50.00	3	\$ 150.00
Apply rust proofing on the adjacent panels.		Sub-contract work.		\$ 50.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.		Sub-contract work.		\$ 750.00
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	50.00	18	\$ 900.00
	Нο	andy rede	Membro Rego	Total

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

- Impact Analysis Consulting Pte Ltd
  Impact Analysis Academy Pte Ltd
  IA Racking Solutions Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171** 

Our reference

20-05-9261

Date

9/6/2020

# **Section C: Summary Table of Total Repair Cost**

Description	Cost	
Damaged Parts Assessment (See section A)	\$6,059.12	
Further discount 20%	\$1,211.82	
Recommended cost of parts	\$4,847.30	(1)
Labour Cost Calculation (See section B)	\$1,875.00	(2)
Total Repair Cost (Round off to hundred)	\$6,700.00	(1) + (2)

We would recommend a sum of	\$6,700.00	and	6	working days for repair.
No further items will be approved with	ithout our expresse	ed written agreem	ent. Any signi	ficant additional
items will be subject to a supplemen	tary report.			
		¥		

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

SPRING- Recognised Certification for Management Consultants

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
  Impact Analysis Academy Pte Ltd
  IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd → Infoknights International Services (Philippines) → IABN Pte Ltd www.iaconsultingsg.com



















