

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|-------------------------------------|-----------------|-------|-----------------------|--|
| | STRIDES AUTOM | OTIVE SERVICES PTE LTD | F | Ref: | CS/SMR21010932/Aqf3n2 | |
| | 60 WOODLANDS I E4SINGAPORE 75 | NDUSTRIAL PARK 17705 | Г | Date: | 21/06/2022 | |
| | | | C | Code: | SMR | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SMB 3599E | Veh. Inspected | | SJN 2611G | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | BUS/10/21/5067 | Excess (\$) | | 0.00 | |
| | Assign From | HUA YEN | Assign Date | | 26/10/2021 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | AUDI Q3 | c.c | | 1395 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2021 | |
| | Chassis No. | WAUZZZF35M1068777 | Colour | | GREY | |
| | Odometer | 10457 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/65 R17 | CONTINENTAL | | 6 mm | |
| | L/H Front Tyre | 215/65 R17 | CONTINENTAL | | 6 mm | |
| | R/H Rear Tyre | 215/65 R17 | CONTINENTAL | | 6 mm | |
| | L/H Rear Tyre | 215/65 R17 | CONTINENTAL | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 23/10/2021 | Inspection Date | | 29/10/2021 | |
| | Survey held at | PREMIUM AUTOMOBILES PTE | LTD | | | |
| | | 55 UBI ROAD 1 . SINGAPORE 408699 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | | |
| 5b. | ESTIMATED NORI | • • • | | | | |