

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS21010935/UTF3N2**Date:** 05/11/2021REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC21A00083200
<b>Claimant Vehicle No :</b>	SMG4222J	<b>Insured Vehicle No :</b>	SNC2341X
Date of Loss:	22/10/2021	Nature of Claim:	TP
		Claim No:	DMPC2100378H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMG4222J</b>	Engine No:	D4FDJD024158
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7211190
Reg. Date:	19/12/2018 (Man. Year: 2018)	Odometer:	233681 km
Colour:	Beige		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	DURATURN 6 mm	Rear Left Side:	DURATURN 6 mm
Front Right Side:	DURATURN 6 mm	Rear Right Side:	DURATURN 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,539.80	1,324.80	1,215.00	47.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	970.00	520.00	34.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,029.80</b>	<b>2,294.80</b>	<b>1,735.00</b>	<b>43.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>(S\$)</b>	4,029.80	1,800.00	2,229.80	55.33
<b>+ GST 7.00/7.00% (S\$)</b>	282.09	126.00	156.09	55.33
<b>Nett Amount (S\$)</b>	<b>4,311.89</b>	<b>1,926.00</b>	<b>2,385.89</b>	<b>55.33</b>

INSPECTION

Date of Assignment:	26/10/2021		
Date Inspected:	27/10/2021	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2021)
<b>Parts:</b>	M1-MPV	KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMG4222J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	549.00 FL	*549.00 FL
2	8		*REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
3	1		*REAR BUMPER CENTRE PAD	Deformed	189.00 FL	*189.00 FL
4	1		*REAR BUMPER LOWER	Deformed	179.00 FL	*179.00 FL
5	1		*REAR BUMPER REVERSE SENSOR (2 Pcs)	Shorted (1 Pc only)	320.00 FL	*160.00 FL
6	2		*REAR BUMPER SIDE RETAINER	Not Necessary	56.00 FL	*- FL
7	2		*REAR BUMPER REFLECTOR	Not Necessary	232.00 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Cracked	367.00 FL	*367.00 FL
9	2		*REAR BUMPER BRACKET	Not Necessary	168.00 FL	*- FL
10	1		*REAR END PANEL	Repair	611.00 FL	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	123.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,822.00</b>	<b>1,472.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	282.20	147.20
<b>Total Parts (\$)</b>	<b>2,539.80</b>	<b>1,324.80</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REINSTALL OF REAR BUMPER REVERSE SENSOR	New	80.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
3	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	700.00	400.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	650.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>1,490.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >