



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDD 7873H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	1,998.00	955.00
1	REAR BUMPER BRACKET LH	NOT NECESSARY	125.00	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	125.00	-
2	REAR REVERSE SENSOR (CENTRE)	DAMAGED (1PC ONLY)	300.00	150.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	755.00	-
1	REAR BUMPER DIFFUSER	CUT	456.00	456.00
1	REAR RIGHT REFLECTOR	NOT NECESSARY	221.00	-
1	REAR RIGHT BOOT	NOT NECESSARY	1,899.00	-
1	REAR BOOT WEATHER STRIPS	NOT NECESSARY	212.00	-
1	REAR BOOT EMBLEMS 'HARRIER'	NOT NECESSARY	145.00	-
1	REAR BOOT EMBLEMS 'LOGO'	NOT NECESSARY	165.00	-
1	REAR BUMPER SPONGE	DAMAGED	117.00	117.00
1	REAR END PANEL ANTENNA SENSOR	DAMAGED	107.00	107.00
	LESS 25% DISCOUNT		-1,656.25	-446.25
			4,968.75	1,338.75
<b><u>LABOUR</u></b>				
	TO FIX & DISMANTLE AND REMOVE DAMAGED FRONT LEFT PORTION; AFFECTED DAMAGED PORTION. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	300.00
	TO APPLY ANTI RUST COAT AND AFFECTED AREAS.		180.00	30.00
	TO CHECK WIRING.		180.00	30.00
	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT. (NPA)	NOT NECESSARY	-	-
	SPRAY PAINTING FOR FRONT LEFT PORTIONS AFFECTED PARTS.		1,000.00	400.00
	REFOCUSING OF THE FRONT HEADLAMP. (NPA)	NOT NECESSARY	-	-
	DIAGNOSE ECU SYSTEM AND RESET ERROR CODE.	NOT NECESSARY	180.00	-
	3D WHEEL ALIGNMENT. (NPA)	NOT NECESSARY	-	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY WATERPROOFING SEALER ON END PANELS.	NOT NECESSARY	120.00	-
			2,460.00	760.00
GRAND TOTAL			7,428.75	2,098.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,600.00

Report Ref No. CS/INC21010937/Atf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.