

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD		Ref:	CS/INC21010937/Atf3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	15/12/2021	
	ATTN: ENG HUEY	HUEY	I	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJA 7614J	Veh. Inspected		SDD 7873H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1148915-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		26/10/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA HARRIER	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTEKB3GH10J004824	Colour		SILVER	
	Odometer	18918 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	235/55 R18	BRIDGESTONE		6 mm	
	L/H Front Tyre	235/55 R18	BRIDGESTONE		6 mm	
	R/H Rear Tyre	235/55 R18	BRIDGESTONE		6 mm	
	L/H Rear Tyre	235/55 R18	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
_						
5.	General Information Accident Date 23/10/2021 Inspect Date / Time 26/10/2021 (03:44 PM)					
	Accident Date	8 Kaki Bukit Avenue 4 #02-13 Pro	<u> </u>	ime	20/10/2021 (03.44 PWI)	
	Survey held at Repairer	AUTO MEGA MALL PTE LTD				
5a.	Remarks					
Ja.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.					
	S)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NOR	STIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				