

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC21010937/Atf3e2		
73 BRAS BASAH ROAD		Date: 15/12/2021		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: ENG HUEY HUEY		Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJA 7614J	Veh. Inspected	SDD 7873H	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1148915-002	Excess (\$)	0.00	
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	26/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTEKB3GH10J004824	Colour	SILVER	
Odometer	18918 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	235/55 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/55 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/10/2021	Inspection Date	26/10/2021	
Survey held at	8 Kaki Bukit Avenue 4 #02-13 Premier			
Repairer	AUTO MEGA MALL PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		