

TP INC Xiao Chen

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: ~~SMW7546X~~ smy67469
 Chassis No:
 Engine No: WBAIV72090249540

Report No :
 Date : 21.09.2021

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	LIST PRICE:	LESS (10%)
1	1	Rear Bumper	Damaged Deformed	\$ 1,988.00	\$ 1,789.20
2	1	Rear Bumper Bracket	Necessary cracked	\$ 155.00	\$ 139.50
3	1	Rear Bumper Diffuser	Damaged cracked	\$ 1,212.00	\$ 1,090.80
4	1	Rear Bumper Reinforcement	Damaged	\$ 635.00	\$ 571.50
5	1	Rear Bumper Reflector	Broken Cut	\$ 212.00	\$ 190.80
6	1	Rear Bumper Grip Chrome Garnish	Damaged Here	\$ 296.00	\$ 266.40
7	1	Rear Right Tail Lamp	Impacted cracked	\$ 989.00	\$ 890.10
8	1	Rear Bumper Towing Cover	Broken Deformed	\$ 125.00	\$ 112.50
9	1	Rear Reverse Sensor Right	Faulty Deformed	\$ 545.00	\$ 490.50
10	1	Rear Right Muffler Exhaust Tip	Scratched Here	\$ 895.00	\$ 805.50
11	1	Rear End Panel	Impacted Repair	\$ 855.00	\$ 769.50
12	1	Rear Boot Weather Strip	Necessary Here	\$ 321.00	\$ 288.90
				\$ 8,228.00	\$ 6,582.40

Total (Parts): \$ 8,228.00 -10% \$ 6,582.40

Labour Charges

26	To fix & dismantle and remove damaged Rear Portions; affected damaged portion.	\$ 900.00	400
27	To apply anti rust coat and affected areas	\$ 180.00	50
28	To check wiring	\$ 180.00	30
29	Welding and cutting of affected panels, including chassis alignment.	\$ 800.00	x
30	Spray painting for Rear Portions affected parts	\$ 1,000.00	500
31	Refocusing of the front headlamp	\$ -	
32	Diagnose ECU system and reset error code.	\$ 180.00	x
33	3D Wheel Alignment	\$ 180.00	x
34	To Apply Waterproofing sealer on End Panels	\$ -	

Total Labour: \$ 3,420.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 10,002.40

Less 20% \$ 8,001.92

AMM PTE LTD

Page 2 of 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Total: 4334.30

N/S: 3 AK

04 Days