



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS3/ASM21010949/Evy3e2 Date: 01/11/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 2307C	Veh. Inspected	GY 8620T
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03KFR	Excess (\$)	0.00
	Assign From	CHAN KIAN CHUAN	Assign Date	26/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN URVAN	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2005
	Chassis No.	JN1MG4E25Z0713609	Colour	SILVER
	Odometer	529366 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	DUNLOP	4 mm
	L/H Front Tyre	195 R15C	DUNLOP	4 mm
	R/H Rear Tyre	195 R15C	DUNLOP	4 mm
	L/H Rear Tyre	195 R15C	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	20/10/2021	Inspection Date	26/10/2021
	Survey held at	1 Soon Lee Street #02-19 Pioneer Centre		
	Repairer	AH SAN MOTOR TRADING & REPAIRING		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	