4/6/22, 9:34 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21010957/UEA3Q2

06/04/2022 Date:

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447

**Claimant Vehicle** SJN7065A Insured Vehicle No: SLM4056C No:

Date of Loss: 24/10/2021 Nature of Claim: TP Claim No: MFL2021D0004638

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SJN7065A** 

Make & Model: HONDA FREED, 1.5 (A) Engine No: L15A2302849 Reg. Date: 25/02/2009 (Man. Year: 2008) Chassis No: GB31002810 Colour: Odometer: 188380 km Silver

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15 Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		18,708.92	9,012.08	9,696.84	51.83
Miscellaneous Items		0.00	0.00	0.00	
Labour		8,970.00	3,950.00	5,020.00	55.96
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	27,678.92	12,962.08	14,716.84	53.17
	Approved Total (Overridden) (S\$)		10,300.00		
	(S\$)	27,678.92	10,300.00	17,378.92	62.79
	+ GST 7.00/7.00% (S\$)	1,937.52	721.00	1,216.52	62.79
	Nett Amount (S\$)	29,616.44	11,021.00	18,595.44	62.79
	+ Loss of Use (14.0 x S	660.00/day) (S\$)	840.00		
	+ Doc/s	Search Fee (S\$)	7.45		
	Ne	ett Liability (S\$)	11,868.45		
	Global Sum	Settlement (S\$)	11,860.00		

**INSPECTION** 

Date of Assignment: 26/10/2021

Falcon-Air Auto Services Pte Ltd (Tampines) Date Inspected: 26/10/2021 Inspected At:

Blk 9006 #01-200 Tampines St 93

Singapore

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### MARKET VALUE

MARKET VALUE: \$19,000

LTA REBATE: \$6,000 NETT VALUE: \$13,000 4/6/22, 9:34 AM Adjuster Report

## **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Dec 2021)

Parts: M1-MPV HONDA FREED 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJN7065A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,525.50 FL	*1,288.30 FL
2	1		*TAILGATE LOGO EMBLEM	Necessary	37.00 FL	*37.00 FL
3	1		*TAILGATE FREED EMBLEM	Necessary	58.00 FL	*58.00 FL
4	1		*TAILGATE GARNISH	Cracked	286.90 FL	*266.50 FL
5	1		*TAILGATE OUTER HANDLE	Distorted	115.00 FL	*68.00 FL
6	2		*REAR NUMBER PLATE LAMP	Cracked (1 PCS ONLY)	97.00 FL	*48.50 FL
7	1		*REAR WIPER LINKAGE	Bent / Jammed	479.40 FL	*479.40 FL
8	1		*TAILGATE LOCK	Dented / Jammed	282.90 FL	*282.90 FL
9	1		*TAILGATE WEATHERSTRIP	Twisted	234.40 FL	*234.40 FL
10	1		*TAILGATE GLASS MOULDING	Necessary	151.20 FL	*151.20 FL
11	1		*TAILGATE INNER TRIM BOARD	Distorted	893.50 FL	*366.10 FL
12	1		*TAILGATE POCKET	Twisted	35.20 FL	*35.20 FL
13	1		*REAR BUMPER	Distorted	1,190.30 FL	*698.50 FL
14	2		*REAR BUMPER SIDE RETAINER	Bent	58.00 FL	*58.00 FL
15	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	29.30 FL	*- FL
16	1		*REAR END PANEL	Badly Dented	576.90 FL	*576.90 FL
17	1		*REAR END PANEL GARNISH	Distorted	135.80 FL	*135.80 FL
18	1		*REAR COMPARTMENT CARPET	Distorted	1,490.70 FL	*842.30 FL
19	1		*REAR COMPARTMENT TRIM	No such part	1,070.30 FL	*- FL
20	1		*REAR COMPARTMENT PANEL	Crumpled	1,453.70 FL	*1,210.30 FL
21	1		*N/S REAR FENDER INNER TRIM	Deformed / Cracked	745.30 FL	*611.20 FL
22	1		*O/S REAR FENDER INNER TRIM	Cracked	745.30 FL	*611.20 FL
23	2		*TAILLAMP	Cracked		*1,313.60 FL
24	2		*REAR FENDER GARNISH	Repair	999.40 FL	*-FL
25	1		*EXHAUST MUFFLER	Repair	1,064.30 FL	*- FL
26	2		*TAILLAMP PANEL	Badly Dented	541.80 FL	*541.80 FL
27	1		*EXHAUST MID PIPE	Not Necessary	989.60 FL	*- FL
28	1		*EXHAUST MUFFLER HEATSHIELD	Not Necessary	145.20 FL	*- FL
29	2		*TAILGATE HINGES	Not Necessary	170.60 FL	*- FL
30	1		*SPARE TYRE FASTENER	Not Necessary	65.20 FL	*-FL
31	2		*REAR FENDER	Repair	2,669.00 FL	*-FL
32	1		*REAR FENDER INNER TRIM TOP	Not Necessary	754.60 FL	*- FL
33	1		*SET TAILGATE GARNISH CLIP	Necessary	50.00 FS	*50.00 FS
34	1		*SET TAILGATE GARNISH CLIP	Repeated	50.00 FS	*-FS
35	1		*REAR NUMBER PLATE	Cracked	45.00 FS	*40.00 FS
36	1		*BTL TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
37	1		*SET TAILGATE GLASS INNER SEAL	Necessary	50.00 FS	*40.00 FS
38	1		*TAILGATE BODY SEALANT	Necessary	80.00 FS	*50.00 FS
39	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
40	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
41	1		*SET REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
42	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*-FS
43	1		*SET REAR COMPARTMENT RUBBER INSULATOR	Necessary	400.00 FS	*200.00 FS
44	1		*SET N/S REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
45	1		*SET O/S REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*30.00 FS
46	1		*SET TAILLAMP CLIPS	Not Necessary	50.00 FS	*-FS

Part No.	Particulars	Condition	Repairer's	Amount
	*SET REAR FENDER GARNISH CLIPS	Not Necessary	50.00 FS	*- F8
	*SET REVERSE CAMERA	Shorted	800.00 FS	*300.00 FS
	*BTLS REAR FENDER GLASS SEALANT	Not Necessary	90.00 FS	*- FS
	*OWNERS BASKET (KIV)	Cracked	200.00 FS	*- F\$
part. S=Spc	Nett. L=ListItemDisc.			
		Sub Total (S\$)	22,789.90	10,995.10
	- List Item Discour	Sub Total (S\$) at on L Items 20.00/20.00% (S\$)	<b>22,789.90</b> 4,080.98	<b>10,995.10</b> 1,983.02
		*SET REVERSE CAMERA  *BTLS REAR FENDER GLASS SEALANT  *OWNERS BASKET	*SET REAR FENDER GARNISH CLIPS  *SET REVERSE CAMERA  *BTLS REAR FENDER GLASS SEALANT  *OWNERS BASKET  (KIV)  Not Necessary  Cracked	*SET REAR FENDER GARNISH CLIPS Not Necessary 50.00 FS *SET REVERSE CAMERA Shorted 800.00 FS *BTLS REAR FENDER GLASS SEALANT Not Necessary 90.00 FS *OWNERS BASKET Cracked 200.00 FS (KIV)

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

Items O CHECK LIGHT AND WIRING ATERTEST TO CHECK FOR LEAKAGE ITI RUST O APPLY BODY SEALANT ON BODY JOINTS EMOVE/REFIT TAILGATE GLASS ANSFER TAILGATE PARTS	New New New New	50.00 50.00 150.00 150.00	0.00
ATERTEST TO CHECK FOR LEAKAGE ITI RUST APPLY BODY SEALANT ON BODY JOINTS EMOVE/REFIT TAILGATE GLASS	New New New	50.00 150.00	20.00 0.00 100.00
ITI RUST O APPLY BODY SEALANT ON BODY JOINTS EMOVE/REFIT TAILGATE GLASS	New New	150.00	100.00
APPLY BODY SEALANT ON BODY JOINTS  EMOVE/REFIT TAILGATE GLASS	New		
MOVE/REFIT TAILGATE GLASS		150.00	
	New		100.00
ANSEED TAIL GATE DADTS	INCV	150.00	120.00
ANDI EN TAILGATE PANTO	New	120.00	60.00
STALL REVERSE SENSOR IN NEW BUMPER	New	100.00	50.00
STALL REVERSE CAMERA	New	200.00	40.00
MOVE/REFIT REAR DASH CAMERA	New	120.00	0.00
MOVE/REFIT INNER TRIMS ,GARNISHES ,SEAT SEATBELT ETC	New	250.00	100.00
CONDUCT CHASSIS ALIGNMENT	New	300.00	0.00
DROP PETROL TANK	New	150.00	0.00
DROP REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	280.00	0.00
PLACE EXHAUST MUFFLER AND MID PIPE	New	200.00	0.00
DIAGNOSE AND CLEAR CODE	New	200.00	60.00
IR N/S REAR FENDER GLASS	New	100.00	0.00
IR O/S REAR FENDER GLASS	New	100.00	0.00
BOUR/PANEL BEATING ,CUT OUT 2PCS FENDER ,END NEL,TAILLAMP PANEL,RR COMPARTMENT PANEL	New	3,500.00	1,800.00
PUTTY AND RESPRAY(1) RR BUMPER (2) END PANEL (3) ILGATE (4) RR COMP PANEL (5) TAILLAMP PANELX2PCS (6) N/S EAR FENDER (7) O/S RR FENDER (8) RR FENDER GARNISHX2PCS ROOF PANEL	New	2,800.00	1,500.00
Gross Labou	ır Cost (S\$)	8,970.00	3,950.00
	MOVE/REFIT REAR DASH CAMERA MOVE/REFIT INNER TRIMS ,GARNISHES ,SEAT SEATBELT ETC CONDUCT CHASSIS ALIGNMENT DROP PETROL TANK DROP REAR UNDERCARRIAGE TO FACILITATE REPAIRS PLACE EXHAUST MUFFLER AND MID PIPE DIAGNOSE AND CLEAR CODE R N/S REAR FENDER GLASS R O/S REAR FENDER GLASS BOUR/PANEL BEATING ,CUT OUT 2PCS FENDER ,END NEL,TAILLAMP PANEL,RR COMPARTMENT PANEL PUTTY AND RESPRAY(1) RR BUMPER (2) END PANEL (3) ILGATE (4) RR COMP PANEL (5) TAILLAMP PANELX2PCS (6) N/S AR FENDER (7) O/S RR FENDER (8) RR FENDER GARNISHX2PCS ROOF PANEL  Gross Labou	MOVE/REFIT REAR DASH CAMERA  MOVE/REFIT INNER TRIMS ,GARNISHES ,SEAT SEATBELT ETC  New  CONDUCT CHASSIS ALIGNMENT  DROP PETROL TANK  New  DROP REAR UNDERCARRIAGE TO FACILITATE REPAIRS  PLACE EXHAUST MUFFLER AND MID PIPE  New  DIAGNOSE AND CLEAR CODE  R N/S REAR FENDER GLASS  New  R O/S REAR FENDER GLASS  New  BOUR/PANEL BEATING ,CUT OUT 2PCS FENDER ,END NEW  NEL,TAILLAMP PANEL,RR COMPARTMENT PANEL  PUTTY AND RESPRAY(1) RR BUMPER (2) END PANEL (3)  New  ILGATE (4) RR COMP PANEL (5) TAILLAMP PANELX2PCS (6) N/S AR FENDER (7) O/S RR FENDER (8) RR FENDER GARNISHX2PCS	STALL REVERSE CAMERA  MOVE/REFIT REAR DASH CAMERA  MOVE/REFIT INNER TRIMS ,GARNISHES ,SEAT SEATBELT ETC  MEW  MOVE/REFIT INNER TRIMS ,GARNISHES ,SEAT SEATBELT ETC  CONDUCT CHASSIS ALIGNMENT  New  MOVE/REFIT INNER TRIMS ,GARNISHES ,SEAT SEATBELT ETC  New  MOVE/REFIT INNER TRIMS ,GARNISHES ,SEAT SEATBELT ETC  New  MOVE/REFIT INNER TRIMS ,GARNISHES ,SEAT SEATBELT ETC  New  MOVE/REFIT INNER TRIMS ,GOUDON  NEW  MOVE/REFIT INNER  MEW  MOVE/REFIT INNER  MOVE/REFIT INNER  MOVE/REFIT INNER  MOVE/REFIT INNER  MOVE/REFIT INNER  MOVE/

< END OF ESTIMATES >