

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Re	f: CS/ASM21010958/Tty3m4	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Da	te: 14/06/2022	
	ATTN: KOH JANIC	E	Co	de: ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGT 505Y	Veh. Inspected	SJF 5764X	
	Policy No.	GA495642	Coverage (\$)	0.00	
	Claim No.	S1M03KQW	Excess (\$)	0.00	
	Assign From	KOH JANICE	Assign Date	26/10/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT 1.3	c.c	1339	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	GE61057158	Colour	RED	
	Odometer	107721 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	FIRENZA	6 mm	
	L/H Front Tyre	195/55 R15	FIRENZA	6 mm	
	R/H Rear Tyre	195/55 R15	FIRENZA	6 mm	
	L/H Rear Tyre	195/55 R15	FIRENZA	6 mm	
4.	1. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	25/10/2021	Inspection Date	27/10/2021	
	Survey held at	1 Kaki Bukit Avenue 6 #01-08 Autobay@Kaki Bukit			
	Repairer	pairer TSL AUTO GARAGE			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days			