TSL Auto Garage Blk 4 Joo Chiat Complex #12-1171 Joo Chiat Road Singapore 420004

SJF5764X Honda Fit

				Estimated			
No	Qt	y Parts Description			Parts Price		
1	1	Rear bumper assy	and the second s	\$	623.70c U	- 490	
2	1	Rear bumper right bracket		\$	45.40 X n		
3	1	of right retainer		\$	42.80 ne		
4	1	Rear bumper tow cover		\$	88.10 de	148	
5	1	Rear tailgate assy		\$	962.80 ht	859	
6	1	Rear tailgate lock mechanism		\$	105.10 X v	M	
7	1			\$	105.10 K ۷ 68.40س	- 48	
8	1	Rear tailgate 'Fit' emblem		\$	هد 68.40	49	
9	1			\$	188.20 W	152	
10	1			\$	68.40 20 188.20 20 483.60 % 7	ſνν.	
11	1	Rear end lower panel		\$	498.60 %	- 465	
12	1			\$	108.60%	_ (0)	
13	1	Rear windscreen glass moulding		\$	سفىر 188.20		
14	1	Rear exhaust muffler assy		\$	862.30 bb-		
15	2	Rear exhaust muffler rubber mounting		\$	36.20 de		
16	1	Rear right fender		\$	1,295.60		
17	1	Rear right shock absorber		\$	387.10×1		
18	1	Rear right wheel hub with bearing assy		\$		m	
19	1	Rear right lower quarter panel		\$	418.80 ×	10.5	
20	1	Rear fender Inner trim board	#477.20	\$	6,722.20		
		less 20%	#432.20	\$	1,344.44	3267	
41	:	The state of the s	335	\$	5,377.76	3367 2 9 4	
		Special Nett Items				204 (
1	10	Rear bumper clips		\$	60.00 8.0	00.	
2	2	Rear bumper reverse sensor		\$ \$	60.00 \$0 300.00 20	nu	
3	4	Rear end lower panel top garnish clips		\$ \$	300.00		
4	1	Rear end lower panel sealant			30.00 2000 140.00 4 00		
5	1	Rear right sports rim		\$			
6	1	Rear right tyre		\$	850.00 KM		
7	1	Rear right fender sealant		\$	300.00 × ~		
8	1	Rear right quarter glass sealant		\$	100.004		
9	1	Rear right quarter glass rubber seal		\$	80.00 204		
10	1	Rear no plate with garnish		\$	80.00 × N		
11	1	Rear windscreen glass sealant		\$	100.00 × n		
12	-	Rear right lower quarter panel sealant		\$	100.00 400		
1 4	1	real right to their quarter pariet scatant	-	\$	100.00 × N	۸.	
			-	\$	2,240.00		
	,	Total parts		\$	7,617.76	330	

TSL Auto Garage Blk 4 Joo Chiat Complex #12-1171 Joo Chiat Road Singapore 420004

JF:	5764X Honda Fit			
		Labour		
No	Description		Charges	
1	Labour for panel beating, cut, weld, straighten rear right affected	\$	1,400.00	Bos
	area and replace rear right damaged parts.			
2	To putty and spray painting rear right portion.	\$	1,400.00	800
3	To check rear lighting and wiring.	\$	50.00	
4	To remove and install rear exhaust muffler assy.		120.00	-
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ \$	140.006	
6	To apply anti rust proofing to rear right affected area.	\$	140.00	40.
7	To remove and install rear bumper reverse sensor.	\$	80.00 '	
8	To remove and install rear windscreen glass to facilitate the repair.	\$	140.00	-
9	To remove and install rear right undercarriage parts.	\$	350.00>	
10	To balance rear right wheel.	\$	50.00 ×	
11	To conduct wheel alignment.	\$	120.00 >	
12	To remove and install rear right quarter glass.	\$	80.00	-
13	Towing service.	\$	100.00	
	Total labour :	\$	4,170.00	
	Taylor 17495749 Total parts: Total labour: Total repair cost: Teaplar elbhantoirem		7,617.76	
	Total labour :	\$	4,170.00	
	Us Purning of the report Total repair cost:	\$:	11,787.76	
	tenfhi elbhantsion		94.24	
	· +days	3	330	
	U	19	80	
	1100			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from the	5·0 15·0 中	4000 Fdays	

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date: