

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21010959/ERA3Q2
Date: 17/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900237219-01
Claimant Vehicle No :	PC6248H	Insured Vehicle No :	EC16E
Date of Loss:	25/10/2021	Nature of Claim:	TP
		Claim No:	0282471065SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6248H		
Make & Model:	MITSUBISHI ROSA, 3.0 D BE641JRMDEB (A)	Engine No:	4P10C58029
Reg. Date:	17/08/2017 (Man. Year: 2017)	Chassis No:	BE641JK30385
Colour:	White	Odometer:	85417 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	7.00- R16	Rear Tyre Size:	7.00- R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,798.96	6,145.05	3,653.91	37.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	2,610.00	750.00	22.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,158.96	8,755.05	4,403.91	33.47
Approved Total (Overridden) (S\$)		7,000.00		

(S\$)	13,158.96	7,000.00	6,158.96	46.80
+ GST 7.00/7.00% (S\$)	921.13	490.00	431.13	46.80
Nett Amount (S\$)	14,080.09	7,490.00	6,590.09	46.80
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,092.00		

INSPECTION

Date of Assignment: 26/10/2021

Date Inspected: 27/10/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Connect 3 (WOODLANDS) (HQ)
 566 Woodlands Road (Mandai Estate)
 Singapore 728697

Adjuster: CHEN TSUE YEE**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	2,981.18 F	*2,533.85 FL
2	2		*REAR BUMPER BRACKET	Not Necessary	350.00 F	*- FL
3	1		*RH SIDE PANEL LOWER OUTER	Dented	2,786.80 F	*2,786.80 FL
4	1		*RH SIDE PANEL LOWER INNER STRUCTURE PANEL	Repair	1,576.80 F	*- FL
5	2		*RH REFLECTOR LAMP ASSY	Broken (1 PCS ONLY)	370.00 F	*185.00 FL
6	1		*RH REAR TYRE	Not Necessary	280.00 F	*- FL
7	1		*REAR RH MUD FLAP	Cut	345.64 F	*345.64 FL
8	1		*EXHAUST TIP	Cut	976.54 F	*976.54 FL
9	1		*EXHAUST BRACKET	Not Necessary	132.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	9,798.96	6,827.83
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	682.78
Total Parts (\$)	9,798.96	6,145.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	APPLY ANTI RUST	New	60.00	30.00
2	CHECK WHEEL ALIGNMENT	New	180.00	60.00
3	CHECK WIRING	New	20.00	20.00
4	LABOUR CHARGES	New	1,500.00	1,300.00
5	SPRAY PAINTING	New	1,600.00	1,200.00
Gross Labour Cost (S\$)			3,360.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >