

ASS. REQ. BY:

Steve

CC4 / A1621010959/193

ASSIGNMENT

From:

Dolo

Estimated Cost:

OD / TR / WS / TP / RES / OD / RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Sum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

PC 6248H

Yr Regn:

17/8/17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Rosa

C.B.

Colour:

White

A/O:

Insured / Std / NI / N

Sp. Reading

85417

T/Radio:

Insured / Std / NI / N

Eng/No:

O/No:

BE 641TR: 39385

Gen. Condi: Good / Fair / Poor / Bught

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / 3/Rlm / 3/0 A/Rlm or

Tyre Size:

Pi

7.00-R16

Ri

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Sal:

4

mm

R/Sal:

4

mm

L/Sal:

4

mm

L/Sal:

4

mm

D.O.A.

25/12/21

O.O.L.

97/12/21

Survey held at

Connect 3

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Reclap or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV - 80K

Time/Date, File, Photo

☐ : Prelim. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trips

Survey Fee

Transportation

S + RS, SI

Excess

Quota

YOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

VVest/anal (\$

Assembly/Print

WV Sum / L/H / P

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

Steve (LKK)
27/10/21, 10.45am

nu M
L/S
6 dys
M K S

QT21/PC6248H/TPC

AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way
#07-16
Singapore 079120

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC6248H

With reference to the above-mentioned, we are pleased to quote as follows:-


No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear bumper / DD	1	2,981.18	2,981.18
2.	Rear bumper bracket X	2	175.00	350.00
3.	RH side panel lower outer / DD	1	2,786.80	2,786.80
4.	RH side panel lower inner structure panel	1	1,576.80	1,576.80
5.	RH reflector lamp assy / DR	2	185.00	370.00
6.	RH rear tyre X	1	280.00	280.00
7.	Rear RH mud flap / cut	1	345.64	345.64
8.	Exhaust Tip / cut (015mm x 1/2)	1	976.54	976.54
9.	Exhaust bracket X	1	132.00	132.00
10.	Apply anti rust	1	60.00	30 60.00
11.	Check wheel alignment	1	180.00	60 180.00
12.	Check wiring	1	20.00	20.00
13.	Labour charges	1	1,500.00	1200 1,500.00
14.	Spray painting	1	1,600.00	1200 1,600.00

	SUB-TOTAL	S\$13,158.96
--	------------------	---------------------

- Price before 7% gst

Thank you.

Yours faithfully,


Winnie Chai
HP: 9850-9666

