

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG21010963/ATCE2

Date: 25/02/2022

REFERENCE

Insured/Claimant:	LIM CHUAN AIK	Policy No:	1900251964		
Date of Loss:	10/07/2021	Nature of Claim:	OD	Claim No:	5397369358SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBX8444A		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK087541
Reg. Date:	29/11/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF5XKA074718
Colour:	Blue	Odometer:	25591 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$161,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,213.00	2,715.28	27,497.72	91.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,372.00	1,242.00	5,130.00	80.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,585.00	3,957.28	32,627.72	89.18
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	35,985.00	3,357.28	32,627.72	90.67
+ GST 7.00/7.00% (S\$)	2,518.95	235.01	2,283.94	90.67
Nett Amount (S\$)	38,503.95	3,592.29	34,911.66	90.67

INSPECTION

Date of Assignment:	18/08/2021		
Date Inspected:	18/08/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	2,251.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Not Necessary	228.00 FS	*- FS
6	1		*RADIATOR GRILLE	Not Necessary	2,326.00 FS	*- FS
7	2		*RADIATOR GRILLE SUPPORT ULTRA SENSOR LH / RH	Not Necessary	102.00 FS	*- FS
8	1		*RADIATOR GRILLE COVER	Not Necessary	189.00 FS	*- FS
9	2		*FRONT AIR GUIDE GRILLE LH / RH	Not Necessary	948.00 FS	*- FS
10	1		*FRONT FOAM FILLIER PIECE	Not Necessary	124.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
12	1		*FRONT BUMPER COVER	Not Necessary	127.00 FS	*- FS
13	1		*STICKER FOR SIGN CAUTION	Not Necessary	14.00 FS	*- FS
14	1		*STICKER FOR AIR CONDITIONER	Not Necessary	8.00 FS	*- FS
15	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
16	2		*FRONT LOCK CARRIER SUPPORT LH / RH	Not Necessary	58.00 FS	*- FS
17	2		*FRONT SENSOR	Not Necessary	0.00 FS	*- FS
			(NPA)			
18	4		*FRONT SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
19	1		*BONNET	Dented	3,312.00 FS	*2,649.60 FS
20	1		*BONNET ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
21	2		*BONNET HINGE LH / RH	Not Necessary	838.00 FS	*- FS
22	2		*BONNET IMPACT PROTECTION LH / RH	Necessary	56.00 FS	*43.68 FS
23	1		*BONNET NOISE INSULATION	Not Necessary	343.00 FS	*- FS
24	2		*BONNET STRICKER LH / RH	Not Necessary	100.00 FS	*- FS
25	2		*BONNET LID LOCK	Not Necessary	427.00 FS	*- FS
26	1		*BONNET RELEASE CABLE	Not Necessary	58.00 FS	*- FS
27	1		*BONNET LOCK COVER	Not Necessary	10.00 FS	*- FS
28	1		*BONNET BOWDEN CABLE CENTER	Not Necessary	58.00 FS	*- FS
29	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
30	2		*LED HEADLIGHT LH / RH	Not Necessary	15,804.00 FS	*- FS
31	2		*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	Not Necessary	396.00 FS	*- FS
32	1		*CORRUGATED PIPE FOR HEADLIGHT WASHER SYSTEM	Not Necessary	86.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE LH	Not Necessary	32.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE RH	Not Necessary	31.00 FS	*- FS
35	1		*RADIATOR AIR GUIDE LH OUTER	Not Necessary	16.00 FS	*- FS
36	1		*RADIATOR AIR GUIDE RH UPPER	Not Necessary	16.00 FS	*- FS
37	1		*RADIATOR AIR GUIDE RH LOWER	Not Necessary	22.00 FS	*- FS
38	1		*CAR PLATE NO.	Not Necessary	60.00 FS	*- FS
39	1		*SUNDRIES	Necessary	350.00 FS	*22.00 FS
40	1		*RADIATOR AIR GUIDE RH OUTER	Not Necessary	16.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 30,213.00 2,715.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	500.00
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES	New	2,500.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			6,372.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >