

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6604M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	NOT NECESSARY	459.40	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	REAR BUMPER REINFORCEMENT BRACKET LH	NOT NECESSARY	138.10	-
1	REAR BUMPER CENTRE MOULDING ASSY	SCRATCHED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	NOT NECESSARY	155.00	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-343.87	-94.65
			1,375.48	378.60
	NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
	LESS 10% DISCOUNT		-18.00	-
			162.00	-
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	SCRATCHED	50.00	50.00
2	REAR FENDER ADV STICKER RH/LH @\$100.00 (SN)	NECESSARY	200.00	200.00
			250.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
			820.00	640.00
	GRAND TOTAL		2,607.48	1,268.60





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,000.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21010965/R1tcn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

h

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser