

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9535P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT FENDER SHIELD LH	SCRATCHED	198.50	198.50
1	FRT FENDER LH	BENT	945.30	945.30
1	FRT FENDER EMBLEM LH	NECESSARY	86.50	86.50
1	FRT BUMPER SIDE RETAINER LH	CRACKED	77.00	77.00
1	HEADLAMP PANEL LH	SERVICEABLE	241.10	-
1	FRONT BUMPER FOG LAMP LH	SERVICEABLE	920.00	-
1	HEADLAMP LH	CRACKED	2,735.28	2,735.28
1	FRONT BUMPER COVER	TORN	499.90	499.90
1	FRONT BUMPER SIDE BRACKET LH	CRACKED	82.30	82.30
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SUPPORT LH	SERVICEABLE	81.70	-
	LESS 25% DISCOUNT		-1,472.40	-1,161.70
			4,417.18	3,485.08
	<u>LABOUR</u>			
	PANEL BEATING.		900.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.		60.00	30.00
	TUFF KOTE.		60.00	40.00
			1,620.00	1,270.00
	GRAND TOTAL		6,037.18	4,755.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,800.00

Report Ref No. NS/INC21010966/R1ucn2


MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor


K.K.LAU CPT(RET)
**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**
REGD Auto Consultant-SAE, Licensed Appraiser
DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.