

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21010967/T1ES3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SHD1265E **Insured Vehicle No :** SMY8984Y
 Date of Loss: 25/10/2021 Nature of Claim: TP Claim No: MFL2021D0004655

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD1265E**
 Make & Model: HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M) Engine No: D4FBGZ105492
 Reg. Date: 14/12/2016 (Man. Year: 2016) Chassis No: TMAD281UVHJ117503
 Colour: Silver Odometer: 399793 km
 Engine Capacity: 1582 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15 Rear Tyre Size: 205/65 R15
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 2,701.55 | 962.41 | 1,739.14 | 64.38 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,500.00 | 530.00 | 970.00 | 64.67 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,201.55 | 1,492.41 | 2,709.14 | 64.48 |
| Approved Total (Overridden) (S\$) | | 1,150.00 | | |
| (S\$) | 4,201.55 | 1,150.00 | 3,051.55 | 72.63 |
| + GST 7.00/7.00% (S\$) | 294.11 | 80.50 | 213.61 | 72.63 |
| Nett Amount (S\$) | 4,495.66 | 1,230.50 | 3,265.16 | 72.63 |
| + Car Rental (3.0 x S\$62.06/day) (S\$) | | 186.18 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 1,424.13 | | |
| Global Sum Settlement (S\$) | | 1,420.00 | | |

INSPECTION

Date of Assignment: 26/10/2021
 Date Inspected: 26/10/2021 Inspected At: Premier Automotive Services Pte Ltd (Changi)
 23 Changi South Ave 2 #01-02
 Singapore 486443
 Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 24 Feb 2022) | |
| Parts: | N/A | HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SHD1265E) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------|------------|------------|
| 1 | 1 | | *TAILGATE LOWER GARNISH | Repair | 362.61 FL | *- FL |
| 2 | 1 | | *TAILGATE WEATHERSTRIP | Not Necessary | 276.98 FL | *- FL |
| 3 | 1 | | *TAILGATE STRIKER | Not Necessary | 36.50 FL | *- FL |
| 4 | 1 | | *EMBLEM CRDI | Necessary | 29.40 FL | *29.40 FL |
| 5 | 1 | | *EMBLEM YUNDAI LOGO | Not Necessary | 29.40 FL | *- FL |
| 6 | 1 | | *REAR BUMPER | Deformed | 811.11 FL | *811.11 FL |
| 7 | 1 | | *REAR BUMPER SPONGE | Not Necessary | 79.20 FL | *- FL |
| 8 | 1 | | *REAR BUMPER REINFORCEMENT | Not Necessary | 815.64 FL | *- FL |
| 9 | 1 | | *REAR BUMPER REINFORCEMENT CENTRE | Not Necessary | 79.20 FL | *- FL |
| 10 | 2 | | *REAR BUMPER N/S & O/S SIDE BRACKET | Not Necessary | 104.40 FL | *- FL |
| 11 | 2 | | *REAR BUMPER N/S & O/S REFLECTOR | Not Necessary | 107.50 FL | *- FL |
| 12 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 48.00 FS | *30.00 FS |
| 13 | 1 | | *SET REVERSE SENSOR | Not Working | 280.00 FS | *200.00 FS |
| 14 | 1 | | *SET TAILGATE STICKERS | Necessary | 100.00 FS | *60.00 FS |
| 15 | 1 | | *SET TAILGATE LOWER GARNISH CLIPS | Not Necessary | 38.00 FS | *- FS |
| 16 | 1 | | *SUNDRY | Not Necessary | 50.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (S\$) | 3,247.94 | 1,130.51 |
| - List Item Discount on L Items 20.00/20.00% (S\$) | 546.39 | 168.10 |
| Total Parts (S\$) | 2,701.55 | 962.41 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM | New | 80.00 | 30.00 |
| 2 | TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING TO KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE OF THE END PANEL ETC | New | 600.00 | 200.00 |
| 3 | TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER ,TAILGATE ,TAILGATE LOWER GARNISH ,END PANEL | New | 700.00 | 300.00 |
| 4 | TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS | New | 120.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 1,500.00 | 530.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >