



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1188A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER ASSY	DEFORMED	499.90	499.90
1	FRONT RH BUMPER BRACKET RH	NOT NECESSARY	77.00	-
1	FRONT FENDER SHIELD RH	TORN	198.50	198.50
1	FRONT HEADLAMP ASSY RH	NOT NECESSARY	2,735.28	-
1	FRONT FOG LAMP RH	NOT NECESSARY	920.00	-
1	FRONT WHEEL RIM	NOT NECESSARY	1,570.55	-
1	FRONT FENDER EMBLEM RH	NECESSARY	86.20	86.20
1	FRT RH FENDER	BENT	945.30	945.30
	LESS 25% DISCOUNT		-1,758.18	-432.48
			5,274.55	1,297.42
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT FENDER RH ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING.		750.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	RESET FRONT WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	CHECK WIRING.	NOT NECESSARY	60.00	-
			1,470.00	850.00
	GRAND TOTAL		6,844.55	2,247.42
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,800.00

Report Ref No. NS/INC21010968/T1vce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.