

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21010970/AEA3Q2**Date:** 19/04/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100505940
<b>Claimant Vehicle No :</b>	GBE7091R	<b>Insured Vehicle No :</b>	SCL1228E
Date of Loss:	19/10/2021	Nature of Claim:	TP
		Claim No:	8616525059SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBE7091R</b>	Engine No:	1KD2597075
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Chassis No:	JTFHT02P100191813
Reg. Date:	08/03/2016 (Man. Year: 2016)	Odometer:	180440 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,939.35	743.10	1,196.25	61.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	880.00	550.00	38.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,369.35</b>	<b>1,623.10</b>	<b>1,746.25</b>	<b>51.83</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>(S\$)</b>	3,369.35	1,200.00	2,169.35	64.38
<b>+ GST 7.00/7.00% (S\$)</b>	235.85	84.00	151.85	64.38
<b>Nett Amount (S\$)</b>	<b>3,605.20</b>	<b>1,284.00</b>	<b>2,321.20</b>	<b>64.38</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	25/10/2021		
Date Inspected:	25/10/2021	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	515.00 FL	*515.00 FL
2	1		*REAR BUMPER RH RETAINER	Not Necessary	65.00 FL	*- FL
3	1		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
4	1		*REAR RH FENDER	Repair	1,500.00 FL	*- FL
5	1		*RH TAILLAMP	Cut	300.80 FL	*300.80 FL
6	1		*APRON PANEL	Deformed	145.00 FL	*145.00 FL
7	1		*RH RIVERT	Not Necessary	30.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>2,585.80</b>	<b>990.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	646.45	247.70
<b>Total Parts (\$)</b>	<b>1,939.35</b>	<b>743.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	600.00	400.00
2	SPRAY PAINTING	New	800.00	450.00
3	WIRING	New	30.00	30.00
			<b>Gross Labour Cost (\$)</b>	<b>880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >