

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21010974/AGA3Q2**Date:** 19/05/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100443245
<b>Claimant Vehicle No :</b>	SLA833R	<b>Insured Vehicle No :</b>	GBE4673G
Date of Loss:	24/10/2021	Nature of Claim:	TP
		Claim No:	6023937234SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLA833R</b>	Engine No:	38735896B38A15A
Make & Model:	BMW 118I, 1.5 MSPT LED HL LED FL (A)	Chassis No:	WBA7K320707F44090
Reg. Date:	23/06/2020 (Man. Year: 2019)	Odometer:	14307 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,222.00	4,546.80	3,675.20	44.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	600.00	2,050.00	77.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,872.00</b>	<b>5,146.80</b>	<b>5,725.20</b>	<b>52.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,872.00</b>	<b>4,100.00</b>	<b>6,772.00</b>	<b>62.29</b>
<b>+ Car Rental (2.0 x S\$100.00/day) (S\$)</b>		200.00		
	<b>Nett Liability (S\$)</b>	<b>4,300.00</b>		

**INSPECTION**

Date of Assignment:	25/10/2021	
Date Inspected:	25/10/2021	Inspected At: Advance Auto Garage 10 Kaki Bukit Road 2, #01-21 First East Centre Singapore 417868
Estimated Period of Repair:	3.0 days	

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,000.00 FS	*1,700.00 FS
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	250.00 F	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Deformed	800.00 FS	*700.00 FS
5	2		*REAR BUMPER REFLECTOR	Not Necessary	96.00 F	*- FL
6	2		*REAR BUMPER SIDE GRILLE	Not Necessary	160.00 FS	*- FS
7	1		*REAR BUMPER REINFORCEMENT	Dented	971.00 F	*971.00 FL
8	1		*REAR BUMPER CENTRE GRILLE	Cracked	154.00 F	*154.00 FL
9	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,040.00 F	*520.00 FL
10	4		*REVERSE SENSOR HOLDER	Not Necessary	112.00 F	*112.00 FL
11	1		*TAILLAMP	N/S Cracked	1,190.00 F	*595.00 FL
12	1		*REAR END PANEL	Not Necessary	1,210.00 F	*- FL
13	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	149.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,222.00</b>	<b>4,782.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	235.20
<b>Total Parts (\$\$)</b>	<b>8,222.00</b>	<b>4,546.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,000.00	300.00
2	SPRAY PAINTING	New	1,000.00	250.00
3	WIRING	New	50.00	0.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	0.00
6	TO PERFORM DIANOGSTIC TEST	New	200.00	0.00
7	TO SPRAY TUFF COAT	New	150.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >