

TP Alg.
Cecilia.

SLA83BR. 2020 June.
BMW 118i 1499CC
WBA7K320707FA4090

Rees Bumper Behind	2000(SN), 1700(SN)
Rees Bumper Clips. NH	30(SN) ✓
Rees Bumper Side Holder x 02 NH	125 x 2 = 250 +
Rees Bumper Lower Garnish. Behind	800(SN) 700(SN)
Rees Bumper Reflector x 02 NH NH	48 x 2 = 96. +
Rees Bumper Side Grille x 02 NH NH	80 x 2 = 160(SN) +
Rees Bumper Reinforcement Dented	971 ✓
Rees Bumper Centre Guide Cracked	154 ✓
Reverse Sensor x 04. 2 pieces dented	320. 260 x 4 = 1040.
Reverse Sensor Holder x 04 NH	28 x 4 = 112 ✓
Tailcap x 02 LH and R	595 595 x 2 = 1190.
Rees End Panel	1210 +
Rees End Panel Sealant	60(SN) +
Rees End Panel Top Garnish	149. +

SLA 833R.

Panel Beating	1000 300
Spry Painting	1000 250
Wiring.	50
To remove reverse sensor	100 50
To remove upholstery.	150 X
To perform diagnostic test.	200 X
To spray tuff coat	150 X

list: 2352

len 10%: 2116.80

S.N: 2430

Labour: 600

total: 5146.80

r/s: 4.1K

4.1K

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: