

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|--|-----------------|-------|-----------------------|--|
| | AXA INSURANCE | PTE LTD | | Ref: | CS/ASM21010977/Aty3e2 | |
| | 8 SHENTON WAY SINGAPORE 0688 | #24-01 AXA TOWER 11 | | Date: | 20/12/2021 | |
| | ATTN: ONG KIAN | THENG DERICK | 1 | Code: | ASM | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | GBF 2274H | Veh. Inspected | | SMR 7853K | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | S1M03KR4 | Excess (\$) | | 0.00 | |
| | Assign From | ONG KIAN THENG DERICK | Assign Date | | 26/10/2021 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HONDA FIT HYBRID | c.c | | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2020 | |
| | Chassis No. | GP51343846 | Colour | | BLUE | |
| | Odometer | 156350 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 185/60 R15 | YOKOHAMA | | 6 mm | |
| | L/H Front Tyre | 185/60 R15 | YOKOHAMA | | 6 mm | |
| | R/H Rear Tyre | 185/60 R15 | YOKOHAMA | | 6 mm | |
| | L/H Rear Tyre | 185/60 R15 | YOKOHAMA | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 26/10/2021 | Inspection Date |) | 26/10/2021 | |
| | Survey held at | ADVANCE AUTO GARAGE | - | | | |
| | | 10 KAKI BUKIT ROAD 2 #03-01 FIRST EAST CENTRE SINGAPORE 417868 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORM | ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days | | | | |