

TP AYA.  
Denise.

SMR7853K.

Honda Fit Hybrid

GPS1343846.

|                                    |           |                   |       |
|------------------------------------|-----------|-------------------|-------|
| Rees Number Plate                  | Bent      | 30(SN)            | ✓     |
| Rees Number Plate Holder           | Dehd      | 30(SN)            | ✓     |
| Rees Number Plate Lamp x 02        | HP        | 54 x 2 = 108      | X     |
| Rees Bumper                        | Dehd      | 529.90            | ✓     |
| Rees Bumper Clips                  | HP        | 30(SN)            | ✓     |
| Rees Bumper Side Holder x 02       | HP        | 24.5 x 2 = 49     | ✓     |
| Rees Bumper Reflector x 02         | HP        | 50.4 x 2 = 100.80 | X     |
| Rees Bumper Reflector Garnish x 02 | RH        | 75.2 x 2 = 150.40 | 75.20 |
| Rees Bumper Lower Garnish Lt       |           | 146.90            | ✓     |
| Rees Bumper Sponge                 | Could     | 105.70            | ✓     |
| Rees End Panel                     | Distorted | 468.50            | ✓     |
| Rees End Panel Top Garnish         | Dehd      | 148.60            | ✓     |
| Rees End Panel Top Garnish Clips   | HP        | 10(SN)            | ✓     |
| Rees End Panel Sealant             | HP        | 60(SN)            | ✓     |
| Rees End Panel Antenna Sensor      | Could     | 95.60             | ✓     |
| Rees End Panel Buzzers             |           | 92.10             | ✓     |

SMR7853K

|                                     |           |                            |                     |
|-------------------------------------|-----------|----------------------------|---------------------|
| Taillamp x 02                       | could     | $366.1 \times 2 = 732.20$  | ✓                   |
| Taillamp Panel x 02                 | RH Dented | $115.90 \times 2 = 231.80$ | ✓ <del>155.90</del> |
| Tailgate                            | Distorted | 898.90                     | ✓                   |
| Tailgate lock                       | Dented    | 195.80                     | ✓                   |
| Tailgate Weatherstripe              | lit       | 148.20                     | ✓                   |
| Tailgate Inner Trim Board           | could     | 341.80                     | ✓                   |
| Tailgate Inner Trim Board clips     | new       | 30(SN)                     | ✓                   |
| Tailgate Outer Chrome Garnish       | could     | 336.20                     | ✓                   |
| Tailgate Outer Chrome Garnish clips | new       | 20(SN)                     | ✓                   |
| Tailgate Side Lamp x 02             | RH could  | $295 \times 2 = 590$       | ✓ <del>295</del>    |
| Tailgate Damper x 02                | Dented    | $189 \times 2 = 378$       | ✓                   |
| Tailgate Hinge x 02                 | new       | $57.5 \times 2 = 115$      | ✓                   |
| Tailgate Wiper Arm                  | 2 new     | 121.40                     | ✓                   |
| Tailgate Wiper Motor                | new       | 396.10                     | ✓                   |
| Tailgate Glass                      | shattered | 880.40                     | ✓                   |
| Tailgate Glass Solar Film           | new       | 250(SN)                    | ✓                   |
|                                     |           | 200(SN)                    | ✓                   |



SMR7853K.

|                                     |                             |                                   |
|-------------------------------------|-----------------------------|-----------------------------------|
| Tailgate Glass Moulding.            | } <del>MR</del>             | 138 ✓                             |
| Tailgate Glass Sealant.             |                             | 60(SN) ✓                          |
| Reverse Sensor                      | Damaged                     | <del>280(SN)</del> 200(SN).       |
| Rear Camera.                        | Damaged                     | <del>480(SN)</del> 380(SN)        |
| Rear Video Recorder.                | Damaged                     | <del>500(SN)</del> 400(SN).       |
| Fit Emblem.                         | } <del>MR</del>             | 42.50 ✓                           |
| Hybrid Emblem.                      |                             | 65 ✓                              |
| Rear Fender x 02                    | RH Buckled                  | 841.50<br>$841.5 \times 2 = 1683$ |
| Rear Fender Inner Shield x 02       | } <del>MR</del>             | $159.8 \times 2 = 319.60 \times$  |
| Rear Fender Inner Shield Clips.     |                             | 50(SN). $\times$                  |
| Rear Fender Inner Trim Board        | Cracked                     | $355.5 \times 2 = 711$ ✓          |
| Rear Fender Inner Trim Board Clips. | <del>MR</del>               | 60(SN) ✓                          |
| Rear Fender Glass Sealant x 02      | <del>RH</del> <del>MR</del> | $40 \times 2 = 80$ (SN) 40(SN)    |
| Spare Tyre Panel                    | Rep's                       | 1072.50 $\times$                  |
| Spare Tyre Panel Top Board          | Deformed                    | 245.90 ✓                          |



SMR7853K.

|                       |       |        |   |
|-----------------------|-------|--------|---|
| Rear Exhaust Pipe     | Rep's | 588.20 | + |
| Rear Exhaust Mounting | NPM   | 32.90  | + |
| Rear RH Door          | Rep's | 851.10 | + |
| Rear RH Door Lock     | NPM   | 262.30 | + |

8077.80

S.N: 1490

6462.24

|                                |                 |      |
|--------------------------------|-----------------|------|
| Panel Beating                  | <del>2400</del> | 1400 |
| Spray Painting                 | <del>1800</del> | 1300 |
| Wiring                         | <del>50</del>   | 30   |
| To remove reverse sensor       | <del>100</del>  | 50   |
| To remove rear camera          | <del>100</del>  | 50   |
| To remove video recorder       | <del>100</del>  | 50   |
| To spray buff coat.            | <del>200</del>  | 120  |
| To remove upholstery.          | <del>150</del>  | 80   |
| To remove exhaust pipe.        | <del>150</del>  | 80   |
| To transfer tailgate fittings. | <del>150</del>  | 80   |

SMR 7853K.

To replace tailgate gl(s)

~~180~~ 150

To vacuum shattered glass shards.

~~150~~ 80

To remove rear hybrid system

250 X

To transfer door fittings.

150 X.

3470

13652

total: 1142224

h/s: 9.1K.

09 Days.

9.1K

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: