

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21010981/ETY3N2**Date:** 05/11/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00082622100
Claimant Vehicle No :	SLL224R	Insured Vehicle No :	SLV8650M
Date of Loss:	18/10/2021	Nature of Claim:	TP
		Claim No:	SNM21D206034/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL224R	Engine No:	LEB5923581
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU31223571
Reg. Date:	10/02/2017 (Man. Year: 2016)	Odometer:	273164 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,327.68	1,934.64	4,393.04	69.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	920.00	2,140.00	69.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,387.68	2,854.64	6,533.04	69.59
Approved Total (Overridden) (\$\$)		2,300.00		
(\$\$)	9,387.68	2,300.00	7,087.68	75.50
+ GST 7.00/7.00% (\$\$)	657.14	161.00	496.14	75.50
Nett Amount (\$\$)	10,044.82	2,461.00	7,583.82	75.50

INSPECTION

Date of Assignment:	27/10/2021	
Date Inspected:	27/10/2021	Inspected At: Lion City Rentals Pte Ltd (HQ) 60 Jalan Lam Huat, #04-35/36 Carros Centre Singapore 737569
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL224R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,450.00 FL	*953.00 FL
2	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	86.80 FL	*86.80 FL
3	1		*REAR TAILGATE HONDA EMBLEM	Not Necessary	81.30 FL	*- FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	84.00 FL	*84.00 FL
5	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
6	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	155.00 FL	*- FL
7	1		*REAR TAILGATE LOCK	Not Necessary	550.00 FL	*- FL
8	1		*REAR END PANEL	Repair	830.00 FL	*- FL
9	1		*REAR END PANEL TOP GARNISH	Not Necessary	155.00 FL	*- FL
10	1		*REAR BUMPER	Crushed	955.00 FL	*762.00 FL
11	1		*REAR SPARE TYRE PANEL	Not Necessary	2,000.00 FL	*- FL
12	1		*REAR SPARE TYRE LUGGAGE TRAY	Not Necessary	480.00 FL	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	180.00 FS	*30.00 FS
14	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
15	1		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
16	1		*WINDSCREEN SEALANT	Necessary	200.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,732.10	2,350.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,404.42	416.16
Total Parts (\$\$)	6,327.68	1,934.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE,REAR END PANEL,REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.ALSO INCLUDE CUTING OUT AND WELDING OF REPLACEMENT SPARE TRYE PANEL	New	1,200.00	400.00
2	TO RESPRAY REAR TAILGATE,REAR BUMPER,END PANEL AND SPARE TYRE PANEL	New	1,000.00	440.00
3	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	160.00	50.00
4	TO CHECK WIRING SYSTEM	New	100.00	30.00
5	TO CONDUCT A STANDARD OF OPEARING PROCEDURES POST REPAIRS SCAN TEST AS A REQUIREMENTS COMPLETION OF COLLISION REPAIRS	New	300.00	0.00
6	TO DEACTIVATE AND ACTIVE HIGH VOLTAGE HYBRID BATTERY AS A SAFETY PRECAUTIONS	New	300.00	0.00
Gross Labour Cost (\$\$)			3,060.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >