



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3640C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	CRACKED	430.90	430.90
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT FENDER RH	BENT	588.80	588.80
1	FRONT FENDER SHIELD RH	TORN	164.70	164.70
1	FRONT FENDER BLUE-DRIVE RH	NECESSARY	26.60	26.60
1	FRONT WHEEL CAP RH	CUT	346.40	346.40
	LESS 20% DISCOUNT		-315.88	-315.88
			1,263.52	1,263.52
<b><u>NETT ITEMS</u></b>				
1	FRT DOOR COMFORTDELGRO RH (N)	NECESSARY	75.00	75.00
1	FRT WESTLAKE TYRE RH (N)	NOT NECESSARY	216.00	-
	LESS 10% DISCOUNT		-29.10	-7.50
			261.90	67.50
<b><u>LABOUR</u></b>				
	PANEL BEATING.		800.00	525.00
	SPRAY PAINTING.		900.00	750.00
	TUFF KOTE.		40.00	30.00
	WHEEL ALIGNMENT.		120.00	60.00
			1,860.00	1,365.00
<b>GRAND TOTAL</b>			<b>3,385.42</b>	<b>2,696.02</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>2,696.02</b>

Report Ref No. NS/INC21010985/T1vcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.