



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 3462G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR O/S	BADLY DENTED	975.00	975.00
1	REAR DOOR INNER LOCK O/S	SHORTED	265.00	265.00
1	REAR DOOR GLASS OUTER MOULDING O/S	NOT NECESSARY	102.00	-
1	REAR DOOR FRAME VISOR O/S	NECESSARY	60.00	60.00
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	987.00	-
	LESS 10% DISCOUNT		-238.90	-130.00
			2,150.10	1,170.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		50.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER O/S.		450.00	380.00
	TO PUTTY & SPRAY PAINTING.		580.00	400.00
			1,130.00	830.00
	GRAND TOTAL		3,280.10	2,000.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/TP21010996/Utf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.