

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/III21011002/UGA3Q2**Date:** 18/03/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MCV0005703\_01

**Claimant Vehicle No :** SJR613T **Insured Vehicle No :** GBE1235H

Date of Loss: 26/10/2021 Nature of Claim: TP Claim No: MCV2021D0004720

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SJR613T**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4896285  
 Reg. Date: 08/06/2009 (Man. Year: 2009) Chassis No: MR053ZEE106146706  
 Colour: Grey Odometer: 256390 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm  
 Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,834.67	3,859.35	2,975.32	43.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,410.00	950.00	40.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,194.67</b>	<b>5,269.35</b>	<b>3,925.32</b>	<b>42.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,194.67</b>	<b>4,200.00</b>	<b>4,994.67</b>	<b>54.32</b>
<b>+ Car Rental (2.0 x S\$100.00/day) (S\$)</b>		200.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,407.45</b>		

**INSPECTION**

Date of Assignment: 27/10/2021

Date Inspected: 27/10/2021 Inspected At:

Choo Motor Spray Painter (HQ)  
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki  
 Bukit  
 Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jan 2022)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJR613T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent / Buckled	1,029.10 FL	*853.70 FL
2	1		*BONNET INNER RUBBER	Necessary	66.50 FL	*66.50 FL
3	2		*BONNET HINGES	Not Necessary	170.00 FL	*- FL
4	1		*BONNET LOCK	Bent	166.10 FL	*145.10 FL
5	1		*FRONT BUMPER	Distorted	651.10 FL	*423.60 FL
6	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	133.10 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	138.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Dented	399.20 FL	*339.70 FL
9	1		*FRONT BUMPER TOP RUBBER	Necessary	68.00 FL	*68.00 FL
10	1		*FRONT BUMPER LOGO	Scratched	68.10 FL	*68.10 FL
11	1		*FRONT GRILLE	Cracked	485.10 FL	*341.10 FL
12	2		*HEADLAMPS	Holder Cracked	1,290.20 FL	*1,163.80 FL
13	1		*FRONT BRACE PANEL	Twisted	151.10 FL	*151.10 FL
14	1		*AIRCON CONDENSER	Bent / Punctured	1,486.10 FL	*1,405.10 FL
15	1		*RADIATOR	Serviceable	1,866.10 FL	*- FL
16	1		*FRONT SUPPORT PANEL	Repair	745.10 FL	*- FL
17	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
18	1		*FRONT BUMPER LICENCE PLATE	Bent	50.00 FS	*40.00 FS
19	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>9,062.90</b>	<b>5,115.80</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	2,228.23	1,256.45
<b>Total Parts (S\$)</b>	<b>6,834.67</b>	<b>3,859.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO REFILL AIR CON GAS	New	120.00	100.00
4	TO RESET & REPROGRAMME SYSTEM	New	180.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	850.00	580.00
6	TO PUTTY & SPRAY PAINTING	New	1,080.00	680.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,360.00</b>	<b>1,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >