

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21008809/GQF3E2-1

Date: 12/11/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SML4236T **Insured Vehicle No :** SMR4285U
Date of Loss: 20/08/2021 Nature of Claim: TP Claim No: MFL2021D0003562

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML4236T**
Make & Model: TOYOTA SIENTA HYBRID, 1.5 X CVT (A) Engine No: 1NZR749413
Reg. Date: 21/05/2019 (Man. Year: 2019) Chassis No: NHP1707159906
Colour: Blue Odometer: 101360 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Firenza 5 mm Rear Left Side: Firenza 5 mm
Front Right Side: Firenza 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,439.00	7,033.92	15,405.08	68.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	2,180.00	1,740.00	44.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,359.00	9,213.92	17,145.08	65.04
Approved Total (Overridden) (S\$)		7,350.00		
Nett Amount (S\$)	26,359.00	7,350.00	19,009.00	72.12

INSPECTION

Date of Assignment: 27/10/2021
Date Inspected: 23/08/2021 Inspected At: SPEEDWERKZ PTE LTD (HQ)
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre
Singapore 147807
Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2021)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML4236T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Distorted	980.50 F	*808.40 FL
2	1		*FRONT BUMPER BRACKET (2PCS)	Necessary (1Pc Only)	290.40 F	*145.20 FL
3	1		*FRONT BUMPER SIDE RETAINER (2PCS)	Necessary (1Pc Only)	130.80 F	*65.40 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	320.50 F	*320.50 FL
5	1		*FRONT BUMPER SPONGE	Cracked	195.60 F	*155.80 FL
6	1		*FRONT BUMPER GARNISH N/S	Cut / Cracked	115.40 F	*115.40 FL
7	1		*FRONT BUMPER CENTRE GARNISH	Cut / Distorted	486.50 F	*486.50 FL
8	1		*FRONT BUMPER CENTRE UNDER GARNISH	Cut / Deformed	268.20 F	*181.60 FL
9	1		*FRONT BUMPER UNDER GARNISH N/S	Cut / Deformed	215.60 F	*125.00 FL
10	1		*FRONT BUMPER GRILLE CHROME GARNISH N/S	Serviceable	194.20 F	*- FL
11	1		*FRONT BUMPER ANGLE SENSOR N/S	Distorted	226.70 F	*226.70 FL
12	1		*FRONT BUMPER LOGO	Necessary	78.20 F	*78.20 FL
13	1		*FRONT BUMPER LOWER LIP	Deformed	225.60 F	*225.60 FL
14	1		*HEADLAMP TOP PANEL	N/S Bent	230.80 F	*115.40 FL
15	2		*HEADLAMP ASSY	Cracked	1,851.20 F	*1,851.20 FL
16	1		*BONNET	Bent	926.70 F	*845.10 FL
17	1		*BONNET LOCK	Serviceable	225.60 F	*- FL
18	1		*FRONT SUPPORT TOP PANEL	Repair	395.20 F	*- FL
19	1		*FRONT FENDER N/S	Bent	786.50 F	*654.60 FL
20	1		*FRONT FENDER INNER SHIELD N/S	Deformed	195.40 F	*195.40 FL
21	1		*FRONT FENDER EMBLEM N/S (HYBRID)	Necessary	76.20 F	*49.80 FL
22	1		*FRONT FENDER QUARTER GARNISH N/S	Deformed	95.40 F	*46.90 FL
23	1		*FRONT DOOR N/S	Repair	1,180.60 F	*- FL
24	1		*FRONT DRI-SHAFT ASSY N/S	Dislodged	1,086.40 F	*1,086.40 FL
25	1		*FRONT LOWER ARM N/S	Bent	386.50 F	*386.50 FL
26	1		*FRONT KNUCKLE ARM N/S	Warped	455.70 F	*455.70 FL
27	1		*FRONT HUB BEARING N/S	Necessary	286.70 F	*210.60 FL
28	1		*FRONT SHOCK ABSORBER N/S	Serviceable	295.20 F	*- FL
29	1		*HYBRID INVERTOR ASSY	Serviceable	9,286.70 F	*- FL
30	1		*SUNDRIES	Serviceable	50.00 FS	*- FS
31	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
32	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	45.00 FS	*30.00 FS
33	1		*FRONT ALLOY RIM N/S R15	Distorted / Cut	580.00 FS	*250.00 FS
34	1		*FRONT TYRE N/S R15	Abraided	195.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,439.00	9,241.90
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	2,207.98
Total Parts (\$\$)	22,439.00	7,033.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,050.00	500.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	80.00	30.00
3	TO REMOVE AND REFIT FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS	New	300.00	200.00
4	TO REMOVE AND REFIT N/S TYRE TO REPLACE N/S RIMS. TO PERFORM TYRE BALANCING	New	80.00	30.00
5	TO DISCONNECT HYBRID WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	180.00	150.00
6	TO RESET AND PROGRAM ON THE HYBRID SYSTEMS	New	480.00	150.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	150.00	60.00
8	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY FRONT BUMPER, BONNET, FRONT SUPPORT TOP PANEL, FRONT FENDER, FRONT DOOR AND OTHER AFFECTED AREA / PANEL	New	1,500.00	1,000.00
9	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	New	100.00	60.00
Gross Labour Cost (\$\$)			3,920.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >