

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011009/BUY3N2**Date:** 17/11/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00060602102

Claimant Vehicle No : SJD3815G **Insured Vehicle No :** GBJ5417Y

Date of Loss: 26/10/2021 Nature of Claim: TP Claim No: SNM21D206146/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJD3815G**

Make & Model: HONDA CROSSROAD, 1.8 (A) Engine No: R18A3010003

Reg. Date: 20/03/2008 (Man. Year: 2008) Chassis No: RT11007430

Colour: White Odometer: 137581 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/40R19 Rear Tyre Size: 275/40R19

Front Left Side: Bridgestone 5 mm Rear Left Side: Continental 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,391.92	6,515.36	2,876.56	30.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	1,930.00	1,900.00	49.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,221.92	8,445.36	4,776.56	36.13
Approved Total (Overridden) (S\$)		5,850.00		
(S\$)	13,221.92	5,850.00	7,371.92	55.76
+ GST 7.00/7.00% (S\$)	925.53	409.50	516.03	55.76
Nett Amount (S\$)	14,147.45	6,259.50	7,887.95	55.76

INSPECTION

Date of Assignment: 28/10/2021

Date Inspected: 28/10/2021 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2021)
Parts: M1-SUV	HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD3815G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	986.50 FL	*753.00 FL
2	2		*BONNET INNER SIDE RUBBER	Not Necessary	92.00 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	175.50 FL	*- FL
4	1		*BONNET INSULATOR CLIPS	Not Necessary	30.00 FL	*- FL
5	1		*BONNET INNER LOCK	Jammed	92.50 FL	*92.50 FL
6	1		*FRONT BUMPER	Dented	1,308.00 FL	*1,106.20 FL
7	2		*FRONT BUMPER SIDE RETAINERS	Necessary	96.00 FL	*61.00 FL
8	1		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
9	1		*FRONT BUMPER SIDE PAD LH	Missing	225.00 FL	*225.00 FL
10	1		*FRONT BUMPER LOWER SKIRT LH	Not Damaged	320.00 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	395.00 FL	*395.00 FL
12	1		*FRONT BUMPER REINFORCEMENT BRACKET LH	Broken	180.00 FL	*125.00 FL
13	1		*FRONT BUMPER REINFORCEMENT GARNISH COVER	No such part	132.50 FL	*- FL
14	1		*FRONT GRILLE	Cut	368.50 FL	*280.00 FL
15	1		*FRONT GRILLE OUTER GARNISH	Broken	351.20 FL	*225.00 FL
16	1		*FRONT GRILLE BADGE	Necessary	56.00 FL	*56.00 FL
17	1		*FRONT GRILLE CLIPS	Necessary	30.00 FL	*30.00 FL
18	1		*HEADLAMP LH	Broken	1,275.00 FL	*1,275.00 FL
19	1		*HEADLAMPS BOTTOM RETAINERS	Broken	136.40 FL	*114.00 FL
20	1		*HEADLAMPS CLIPS	Necessary	40.00 FL	*30.00 FL
21	1		*FRONT FENDER LH	Dented	593.00 FL	*525.20 FL
22	1		*FRONT FENDERS ARCH GARNISH	Bent	272.30 FL	*272.30 FL
23	1		*FRONT FENDERS ARCH GARNISH CLIPS	Necessary	60.00 FL	*30.00 FL
24	1		*FRONT FENDERS TOP GARNISH LH	Broken	79.20 FL	*79.20 FL
25	1		*FRONT FENDERS TOP GARNISH CLIPS	Necessary	30.00 FL	*30.00 FL
26	1		*FRONT FENDERS INNER SHIELD LH	Broken	132.00 FL	*132.00 FL
27	1		*FRONT FENDERS INNER SHIELD CLIPS	Necessary	60.00 FL	*30.00 FL
28	1		*SUPPORT PANEL	Dented	691.50 FL	*634.00 FL
29	1		*SUPPORT PANEL TOP GARNISH	Broken	183.60 FL	*56.40 FL
30	1		*SUPPORT PANEL TOP GARNISH CLIPS	Necessary	40.00 FL	*30.00 FL
31	1		*SUPPORT PANEL TOP STOPPER	Not Necessary	44.00 FL	*- FL
32	1		*FRONT LH SHOCK ABSORBER	Bent	321.70 FL	*321.70 FL
33	1		*FRONT LH SHOCK ABSORBER TOP MOUNTING	Necessary	195.00 FL	*105.60 FL
34	1		*FRONT LH LOWER ARM	Bent	460.00 FL	*425.10 FL
35	1		*FRONT LH KNUCKLE ARM	Bent	450.00 FL	*450.00 FL
36	1		*FRONT LH BEARING	Jammed	225.00 FL	*225.00 FL
37	1		*FRONT LH TIE ROD END	Not Damaged	125.00 FL	*- FL
38	1		*FRONT LH RIM	Not Damaged	850.00 FS	*- FS
39	1		*FRONT LH TYRE	Not Damaged	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,452.40	8,144.20
- List Item Discount on L Items 20.00/20.00% (\$)	2,060.48	1,628.84
Total Parts (\$)	9,391.92	6,515.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON ACCIDENT PORTION	New	1,600.00	800.00
2	SPRAY PAINTING ON ACCIDENT PORTION	New	1,500.00	800.00
3	CHECK WIRING	New	50.00	0.00
4	ANTI RUST	New	100.00	0.00
5	REMOVE AND INSTALL AIR CON & TOP UP GAS	New	150.00	120.00
6	WHEEL ALIGNMENT	New	150.00	60.00
7	TO REMOVE & REFIT UNDERCARRIAGE	New	280.00	150.00
			Gross Labour Cost (\$\$)	1,930.00
				3,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >