

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 8076Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEADLAMP (CONSISTENT)	NOT NECESSARY	545.00	-
1	HEADLAMP COWLING (CONSISTENT)	NOT NECESSARY	280.00	-
1	FRONT COWLING (CONSISTENT)	NOT NECESSARY	250.00	-
1	FRONT COVER PANEL INNER (CONSISTENT)	NOT NECESSARY	85.00	-
1	FUEL TANK (CONSISTENT)	TO REPAIR SEE LABOUR	810.00	-
1	FUEL TANK OUTER COVER O/S (CONSISTENT)	CUT	410.00	345.00
1	FRONT SIDE COVER O/S (CONSISTENT)	CUT	300.00	250.00
1	MIRROR O/S (CONSISTENT)	CUT	136.00	110.00
1	FRONT FENDER (CONSISTENT)	NOT NECESSARY	85.00	-
2	FRONT FORKS @\$650.00(CONSISTENT)	O/S BENT / TWISTED	1,300.00	485.00
1	FRONT FORK BRACKET (CONSISTENT)	BENT	225.00	225.00
1	FRONT FORK BEARING (CONSISTENT)	NECESSARY	60.00	60.00
1	FRONT WHEEL SHAFT (CONSISTENT)	CUT / BENT	50.00	38.00
1	FRONT WHEEL (CONSISTENT)	CUT / BENT	545.00	480.00
1	FRONT WHEEL BEARING (CONSISTENT)	NECESSARY	60.00	45.00
1	HANDLE BAR (CONSISTENT)	BENT	192.00	182.00
2	HANDLE GRIPS @\$60.00(CONSISTENT)	O/S TORN	120.00	60.00
1	MASTER PUMP (CONSISTENT)	NOT NECESSARY	195.00	-
1	METER PANEL COVER (CONSISTENT)	NOT NECESSARY	82.00	-
2	FRONT FOOTRESTS @\$166.00(CONSISTENT)	O/S CUT	332.00	60.00
1	FRONT FOOTREST BRACKET (CONSISTENT)	BENT	300.00	145.00
1	SIDE STAND (CONSISTENT)	NOT NECESSARY	80.00	-
1	MAIN STAND (CONSISTENT)	NOT NECESSARY	190.00	-
2	REAR FOOT RESTS @\$85.00(CONSISTENT)	O/S CUT	170.00	60.00
1	REAR EXHAUST (CONSISTENT)	TO REPAIR SEE LABOUR	800.00	-
1	REAR EXHAUST OUTER COVER (CONSISTENT)	CUT	244.00	180.00
1	REAR SEAT COVER O/S (CONSISTENT)	CUT	468.00	395.00
1	SIDE COVER CENTRE O/S (CONSISTENT)	CUT	250.00	205.00
1	BRAKE PEDAL (CONSISTENT)	сит	150.00	122.00

Report Ref No. CC4/ASM21011012/Ups3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	FRONT SIGNAL LAMP O/S (CONSISTENT)	CUT	90.00	70.00
1	REAR SIGNAL LAMP O/S (CONSISTENT)	CUT	85.00	70.00
	LESS 10% DISCOUNT		-	-358.70
			8,889.00	3,228.30
	SPECIAL NETT ITEMS			
1	REAR LICENCE PLATE (SN)(CONSISTENT)	NOT NECESSARY	10.00	-
1	FRONT LICENCE PLATE (SN)(CONSISTENT)	NOT NECESSARY	10.00	-
1	REAR TOP BOX (SN)(CONSISTENT)	CUT	680.00	450.00
1	SET REAR TOP BOX RACK (SN)(CONSISTENT)	BENT	250.00	180.00
1	SET FRONT FAIRING STICKER (SN)(CONSISTENT)	NECESSARY	280.00	100.00
			1,230.00	730.00
	<u>LABOUR</u>			
	TO STRAIGHTEN BODY ALIGNMENT.	NOT NECESSARY	380.00	-
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF FUEL TANK AND REAR FOOT RESTS.		350.00	280.00
	TO PUTTY & SPRAY PAINTING.		500.00	150.00
			1,230.00	430.00
	GRAND TOTAL		11,349.00	4,388.30
	RECOMMENDED COST OF LUMP SUM REPAIRS			3,500.00

Report Ref No. CC4/ASM21011012/Ups3q2

CHUA KANG SENG

Licensed Appraiser

(TO ITS PRE-ACCIDENT CONDITION)