

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011016/KVY3N2**Date:** 24/11/2021REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00002152103

**Claimant Vehicle
No :** SJT4169Y**Insured Vehicle
No :** CB6899M

Date of Loss: 24/10/2021

Nature of Claim: TP

Claim
No: SNM21D206086/C02/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJT4169Y**

Make & Model: VOLKSWAGEN JETTA, 1.4 TSI (A)

Engine No: CAX310033

Reg. Date: 08/10/2009 (Man. Year: 2009)

Chassis No: WVVZZZ1KZ9U021319

Colour: Metallic Blue

Odometer: 194464 km

Engine Capacity: 1390 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,294.40	2,852.78	1,441.62	33.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	1,470.00	1,430.00	49.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,194.40	4,322.78	2,871.62	39.91
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	7,194.40	3,450.00	3,744.40	52.05
+ GST 7.00/7.00% (S\$)	503.61	241.50	262.11	52.05
Nett Amount (S\$)	7,698.01	3,691.50	4,006.51	52.05

INSPECTION

Date of Assignment: 27/10/2021

Date Inspected: 28/10/2021 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Nov 2021)
Parts:	143	VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT4169Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER O/S	Bent	978.00 FL	*978.00 FL
2	1		*REAR FENDER AIR VENT O/S	Serviceable	179.00 FL	*- FL
3	1		*REAR FENDER COWLING O/S	Serviceable	228.00 FL	*- FL
4	1		*REAR WINDSCREEN MOULDING	Necessary	313.00 FL	*250.80 FL
5	1		*REAR BUMPER	Buckled/Dented	1,364.00 FL	*1,088.40 FL
6	1		*REAR BUMPER SIDE RETAINER	O/s Distorted	566.00 FL	*100.50 FL
7	1		*TAILLAMP O/S	Cut	698.00 FL	*600.95 FL
8	1		*REAR FENDER SEALANT O/S	Necessary	80.00 FS	*30.00 FS
9	10		*REAR FENDER COWLING CLIPS O/S	Not Necessary	55.00 FS	*- FS
10	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
11	12		*REAR BUMPER CLIPS	Necessary	66.00 FS	*66.00 FS
12	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,727.00	3,154.65
- List Item Discount on L Items 10.00/10.00% (S\$)	432.60	301.87
Total Parts (S\$)	4,294.40	2,852.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	700.00
2	SUPPLY SPRAY PAINT MATERIALS AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,200.00	500.00
3	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK	New	150.00	120.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS OF TAILLAMPS	New	50.00	20.00
5	TO REMOVE AND REFIT INTERIOR UPHOLSTERY,INNER TRIM,INNER GARNISH,MOULDINGS TO FACILITATE REPAIR	New	200.00	100.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	30.00
Gross Labour Cost (\$\$)			2,900.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >