

Repair Estimate

# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721  
Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Not Notified  
C/Pay 83700h  
Recovery After Paint  
5days

Make/Model: VOLKSWAGEN JETTA TSI  
Engine/Chassis No.: WVWZZZ1KZ9U021319  
Date of accident:  
Damaged area: O/S

Date: 28/10/2021  
Claim Type: TP  
VRN: **SJT4169Y**



| List items    |                                   |     |             |             |
|---------------|-----------------------------------|-----|-------------|-------------|
| S/N           | Parts description                 | QTY | UNIT PRICE  | AMOUNT      |
| 1             | Rear fender o/s                   | 1   | \$ 978.00   | \$ 978.00   |
| 2             | Rear fender air vent o/s          | 1   | \$ 179.00   | \$ 179.00   |
| 3             | Rear fender cowling o/s           | 1   | \$ 228.00   | \$ 228.00   |
| 4             | Rear windscreen moulding 250.80   | 1   | \$ 313.00   | \$ 313.00   |
| 5             | Rear bumper 1088.90               | 1   | \$ 1,364.00 | \$ 1,364.00 |
| 6             | Rear bumper side retainer @100.50 | 2   | \$ 283.00   | \$ 566.00   |
| 7             | Taillamp o/s 600.95               | 1   | \$ 698.00   | \$ 698.00   |
| Subtotal      |                                   |     |             | \$ 4,326.00 |
| List discount |                                   |     |             | 10.00%      |
| Total         |                                   |     |             | \$ 3,893.40 |

| Special nett items |                               |     |            |           |
|--------------------|-------------------------------|-----|------------|-----------|
| No.                | Parts description             | QTY | UNIT PRICE | AMOUNT    |
| 1                  | Rear fender sealant o/s       | 1   | \$ 80.00   | \$ 80.00  |
| 2                  | Rear fender cowling clips o/s | 10  | \$ 5.50    | \$ 55.00  |
| 3                  | Rear windscreen sealant       | 1   | \$ 150.00  | \$ 150.00 |
| 4                  | Rear bumper clips             | 12  | \$ 5.50    | \$ 66.00  |
| 5                  | Sundries                      | 1   | \$ 50.00   | \$ 50.00  |
| Total              |                               |     |            | \$ 401.00 |

| Labour |                                                                                                                                    |           |             |
|--------|------------------------------------------------------------------------------------------------------------------------------------|-----------|-------------|
| No.    | Description                                                                                                                        | Work unit | Amount      |
| 1      | To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts. | 6         | \$ 1,200.00 |

# Repair Estimate

|                      |                                                                                                                        |      |    |          |       |
|----------------------|------------------------------------------------------------------------------------------------------------------------|------|----|----------|-------|
| 2                    | Supply spray paint materials and necessary items to respray affected area / panel.                                     | 6    | \$ | 1,200.00 | 500l  |
| 3                    | To remove and refit rear windscreen to facilitate repair work.                                                         | 0.75 | \$ | 150.00   | 1200h |
| 4                    | To disconnect wire harness of electrical components to facilitate repairs, reconnect and check functions of taillamps. | 0.25 | \$ | 50.00    | 20l   |
| 5                    | To remove and refit interior upholstery, inner trim, inner garnish, mouldings to facilitate repair.                    | 1    | \$ | 200.00   | 100l  |
| 6                    | To rust proof all affected portions after repair.                                                                      | 0.5  | \$ | 100.00   | 30l   |
| Total labour         |                                                                                                                        |      | \$ | 2,900.00 |       |
| Estimate Grand Total |                                                                                                                        |      | \$ | 7,194.40 |       |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: