

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21011017/KPA3Q2**Date:** 02/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100332627
<b>Claimant Vehicle No :</b>	SMY3179M	<b>Insured Vehicle No :</b>	SFA1966E
Date of Loss:	25/10/2021	Nature of Claim:	TP
		Claim No:	0253570060SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMY3179M</b>	Engine No:	2ZR2G83227
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU303091584
Reg. Date:	26/02/2021 (Man. Year: 2020)	Odometer:	60940 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,889.70	2,115.45	4,774.25	69.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,290.00	1,150.00	9,140.00	88.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,179.70</b>	<b>3,265.45</b>	<b>13,914.25</b>	<b>80.99</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,202.58</b>	<b>228.58</b>	<b>974.00</b>	<b>80.99</b>
<b>Nett Amount (S\$)</b>	<b>18,382.28</b>	<b>3,494.03</b>	<b>14,888.25</b>	<b>80.99</b>
<b>+ Car Rental (4.0 x S\$65.00/day) (S\$)</b>		260.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,761.48</b>		

INSPECTION

Date of Assignment:	26/10/2021		
Date Inspected:	26/10/2021	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	22.00 FL	*- FL
4	1		*GUARD ,REAR BUMPER ,CENTER	Bent	374.50 FL	*374.50 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	132.60 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
7	1		*REFLECTOR ASSY ,REFIX ,LH	Serviceable	39.00 FL	*- FL
8	1		*REFLECTOR ASSY ,REFIX ,RH	Serviceable	39.00 FL	*- FL
9	1		*PANEL SUB-ASSY ,BACK DOOR	Bent	1,147.80 FL	*1,147.80 FL
10	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME ,NO.2	Not Necessary	54.60 FL	*- FL
11	1		*PLATE ,BACK DOOR NAME ,NO.1	Not Necessary	54.60 FL	*- FL
12	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Not Necessary	47.90 FL	*- FL
13	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Serviceable	913.60 FL	*- FL
14	1		*BOARD ASSY ,BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
15	1		*WEATHERSTRIP ,BACK DOOR	Serviceable	372.30 FL	*- FL
16	1		*COVER ,FLOOR UNDER NO.1 LH	Serviceable	175.10 FL	*- FL
17	1		*COVER ,FLOOR UNDER NO.2 RH	Serviceable	241.90 FL	*- FL
18	1		*COVER ,REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
19	1		*COVER DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
20	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
21	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
22	1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
23	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
24	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
25	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
26	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*50.00 FS
27	2		*WINDSCREEN SEALANT	Necessary	150.00 FS	*80.00 FS
28	1		*WINDSCREEN MOULDING	Necessary	200.00 FS	*200.00 FS
29	1		*WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	*30.00 FS
30	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
31	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
32	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	*- FS
33	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
34	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
35	1		*SET BUMPER CLIP FRT	Not Necessary	95.00 FS	*- FS
36	1		*REAR NUMBER PLATE WITH MOULDING	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,499.60</b>	<b>2,700.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	1,609.90	585.15
<b>Total Parts (\$)</b>	<b>6,889.70</b>	<b>2,115.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	180.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMINGS ,GARNISH ,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,200.00	400.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING ,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT ,VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
12	TOWING FEES	New	150.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
14	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
16	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
17	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
18	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
19	TO LIFT-UP /OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
20	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS -MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
21	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>10,290.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >