

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011026/VGA3Q2**Date:** 08/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100456893
Claimant Vehicle No :	SFC988M	Insured Vehicle No :	SLB1988R
Date of Loss:	25/10/2021	Nature of Claim:	TP
		Claim No:	8011729118SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFC988M	Engine No:	08288218N55B30A
Make & Model:	BMW 640I, 3.0 (A)	Chassis No:	WBALW72020DK15564
Reg. Date:	12/09/2012 (Man. Year: 2012)	Odometer:	60358 km
Colour:	Silver		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/30 R20	Rear Tyre Size:	275/30 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,971.70	6,998.62	4,973.08	41.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,910.00	600.00	2,310.00	79.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,881.70	7,598.62	7,283.08	48.94
Approved Total (Overridden) (\$\$)		6,100.00		
(\$\$)	14,881.70	6,100.00	8,781.70	59.01
+ GST 7.00/7.00% (\$\$)	1,041.72	427.00	614.72	59.01
Nett Amount (\$\$)	15,923.42	6,527.00	9,396.42	59.01
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	27/10/2021	
Date Inspected:	28/10/2021	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	3.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	1,815.00 FL	*1,513.40 FL
2	1		*FRONT BUMPER RETAINER LH	Necessary	132.00 FL	*30.00 FL
3	1		*FRONT BUMPER PDC	Cut	275.00 FL	*275.00 FL
4	1		*FRONT BUMPER LOWER GRILLE	Scratched	143.00 FL	*143.00 FL
5	1		*FRONT HEADLAMP LH	Scratched	2,640.00 FL	*2,640.00 FL
6	1		*FRONT HEADLAMP BRACKET LH	Cut	154.00 FL	*128.45 FL
7	1		*FRONT SIGNAL LAMP LH	Cut	260.00 FL	*260.00 FL
8	1		*FRONT NOZZLE	Serviceable	209.00 FL	*- FL
9	1		*FRONT NOZZLE COVER	Scratched	77.00 FL	*77.00 FL
10	1		*FRONT SHOCK ABSORBER LH	Serviceable	1,815.00 FL	*- FL
11	1		*FRONT KNUCKLE ARM LH	Serviceable	770.00 FL	*- FL
12	1		*FRONT KNUCKLE ARM BEARING LH	Serviceable	528.00 FL	*- FL
13	1		*FRONT LOWER ARM LH	Bent	748.00 FL	*310.00 FL
14	1		*FRONT UPPER ARM LH	Bent	605.00 FL	*486.70 FL
15	1		*FRONT RIM LH	Cut	1,980.00 FL	*1,200.00 FL
16	1		*FRONT HEADLAMP TINTING	Necessary	200.00 FS	*100.00 FS
17	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
18	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	50.00 FS	*30.00 FS
19	1		*FRONT BUMPER SPONGE	Cut	135.00 FL	*135.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					12,586.00	7,358.55
- List Item Discount on L Items 5.00/5.00% (\$\$)					614.30	359.93
Total Parts (\$\$)					11,971.70	6,998.62

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	20.00
2	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	New	200.00	60.00
3	REMOVE AND REPLACE REAR UNDERCARRIAGE	New	200.00	40.00
4	RE-PROGRAMME AFTER REPAIR	New	300.00	50.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	200.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	200.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$\$)			2,910.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >