

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011027/APA3Q2**Date:** 04/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900085698
Claimant Vehicle No :	EZ68J	Insured Vehicle No :	SML1247G
Date of Loss:	24/10/2021	Nature of Claim:	TP
		Claim No:	9508050526SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EZ68J	Engine No:	1NZD184320
Make & Model:	TOYOTA ALLION, 1.5 (A)	Chassis No:	NZT2603032480
Reg. Date:	31/10/2008 (Man. Year: 2008)	Odometer:	295640 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,683.92	2,420.82	2,263.10	48.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	1,350.00	2,360.00	63.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,393.92	3,770.82	4,623.10	55.08
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	8,393.92	3,000.00	5,393.92	64.26
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,507.45		

INSPECTION

Date of Assignment:	27/10/2021	Ace Autolution Pte Ltd (KAKI BUKIT)
Date Inspected:	28/10/2021 Inspected At:	13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Estimated Period of Repair:	5.0 days	Singapore 417807

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Not Necessary	977.50 FL	*- FL
2	1		*REAR BOOTLID LOGO	Necessary	71.00 FL	*71.00 FL
3	1		*REAR BOOTLID CHROME	Not Necessary	214.00 FL	*- FL
4	1		*REAR BOOTLID WEATHERSTRIP	Cut	154.80 FL	*154.80 FL
5	1		*REAR BOOTLID LOCK	Not Necessary	320.00 FL	*- FL
6	2		*REAR BOOTLID HINGE LH & RH	Not Necessary	229.00 FL	*- FL
7	1		*REAR BUMPER RH	Deformed	1,243.00 FL	*1,080.00 FL
8	1		*REAR BUMPER SIDE RETAINER LH & RH	N/S Damaged	202.00 FL	*58.00 FL
9	1		*REAR BUMPER REFLECTOR LH & RH	N/S Cracked	180.00 FL	*95.00 FL
10	1		*REAR BUMPER BRACKET LH & RH	N/S Dented	170.00 FL	*85.00 FL
11	1		*REAR END PANEL	Dented	598.00 FL	*598.00 FL
12	1		*REAR END PANEL TOP GARNISH	Deformed	197.00 FL	*197.00 FL
13	1		*REAR TAILLAMP LH & RH	N/S Cracked	694.60 FL	*347.30 FL
14	2		*REAR TAILLAMP BRACKET LH & RH	Not Necessary	106.00 FL	*- FL
15	1		*ANTENNA SENSOR	Cracked	155.00 FL	*155.00 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
17	1		*SET REAR CAR PLATE WITH COVER	Not Necessary	70.00 FS	*- FS
18	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
19	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
					<hr/>	
					Sub Total (S\$)	6,061.90 3,131.10
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,377.98 710.28
					<hr/>	
					Total Parts (S\$)	4,683.92 2,420.82
					<hr/>	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	600.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	600.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	120.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	200.00	60.00
5	TO CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
6	TO REMOVE AND REFIX CUSHION AND INNER TRIM	New	150.00	60.00
7	TO REMOVE REAR BOOT MECHANISM	New	120.00	0.00
Gross Labour Cost (S\$)			3,710.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >