1/13/22, 4:07 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21011028/EEA3Q2

**Date:** 13/01/2022

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993577

Claimant Vehicle XE762Z Insured Vehicle No : SMV8594E

Date of Loss: 18/08/2021 Nature of Claim: TP Claim No: 1341051169SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: XE762Z

Make & Model: ISUZU FXZ77M, 9.8 D (M) Engine No: 6UZ1487338

Reg. Date: 26/06/2015 (Man. Year: 2014) Chassis No: JALFXZ77ME7000089

Colour: White Odometer: 514363 km

Engine Capacity: 9839 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,189.00	122.00	1,067.00	89.74
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,400.00	800.00	600.00	42.86
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	2,589.00	922.00	1,667.00	64.39
	+ GST 7.00/7.00% (S\$)	181.23	64.54	116.69	64.39
	Nett Amount (S\$)	2,770.23	986.54	1,783.69	64.39
	+ Loss of Use (2.0 x S	\$\$150.00/day) (S\$)	300.00		
	+ Do	c/Search Fee (S\$)	7.45		
		Nett Liability (S\$)	1,293.99		
	Global Sui	m Settlement (S\$)	1,290.00		

**INSPECTION** 

Date of Assignment: 27/10/2021

Shingda Equipment Leasing Pte Ltd (HQ)

Date Inspected: 09/11/2021 Inspected At: 10 KRANJI CRESCENT

10 KRAINJI CRESCEINT

Singapore 728660

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,000.00 FL	*- FL
2	1		*FRONT STEP LOWER GARNISH LHS	Cut	120.00 FL	*120.00 FL
3	1		*FRONT STEP LOWER PANEL LHS	Not Necessary	220.00 FL	*- FL
4	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Fra	nchise	part. S=SpcNe	tt. L=ListItemDisc.	_		
				Sub Total (S\$)	1,390.00	140.00
- List Item Discount on L Items 15.00/15.00% (S\$)			201.00	18.00		
				Total Parts (S\$)	1,189.00	122.00
			Report was unsubmitted during	this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Lab	our Items				
1	TO REMOVE & REFIT DAMAGED PARTS ,CUT ,WELD ,PANEL BEAT ,STRAIGHTEN & REALIGN ETC	New	900.00	500.00	
2	TO PUTTY ,CLEAN SPRAY PAINT & POLISH ETC	New	500.00	300.00	
	Gross Labour Cost (S\$)		1,400.00	800.00	
	Report was unsubmitted during this print-out.				

< END OF ESTIMATES >