

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011030/EEA3Q2**Date:** 16/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100132986
Claimant Vehicle No :	FBR7602Z	Insured Vehicle No :	SGS6130K
Date of Loss:	21/10/2021	Nature of Claim:	TP
		Claim No:	5749693948SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR7602Z	Engine No:	ZT158MJAL1100091
Make & Model:	ZONTES ZT150G, 150cc	Chassis No:	LD3PDK6A3L1606188
Reg. Date:	08/10/2020 (Man. Year: 2020)	Odometer:	11479 km
Colour:	Black		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	130/10-17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,727.70	1,520.70	207.00	11.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	395.00	345.00	50.00	12.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,122.70	1,865.70	257.00	12.11
+ GST 7.00/7.00% (\$\$)	148.59	130.60	17.99	12.11
Nett Amount (\$\$)	2,271.29	1,996.30	274.99	12.11
+ Loss of Use (3.0 x S\$30.00/day) (\$\$)		90.00		
Nett Liability (\$\$)		2,086.30		

INSPECTION

Date of Assignment:	27/10/2021	
Date Inspected:	27/10/2021	Inspected At: Choong Kok Agency Pte Ltd (Jurong) Block 343, Jurong East Street 31, #01-63 Singapore 600343
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	80.00 FL	*80.00 FL
2	1		*HAND GUARD RH	Cut	68.00 FL	*68.00 FL
3	1		*GUARD SILDER RH	Cut	58.00 FL	*58.00 FL
4	1		*ENGINE GUARD RH	Not Necessary	90.00 FL	*- FL
5	1		*FRONT FOOTREST RH	Cut	55.00 FL	*55.00 FL
6	1		*BRAKE PEDAL RH	Cut	85.00 FL	*85.00 FL
7	1		*FRONT FENDER	Cut	95.00 FL	*80.00 FL
8	1		*SET FRONT FORK RH	Bent	220.00 FL	*200.00 FL
9	1		*SET FRONT FORK LH	Bent	220.00 FL	*200.00 FL
10	1		*CENTRE STEERING STAY	Bent	158.00 FL	*158.00 FL
11	1		*SET STEERING CONE	Necessary	90.00 FL	*70.00 FL
12	1		*REAR SIGNAL RH	Cut	28.00 FL	*28.00 FL
13	1		*MUFFLER TAIL COVER REAR	Cut	58.00 FL	*58.00 FL
14	1		*FUEL TANK BLACK	Dented	250.00 FL	*220.00 FL
15	1		*FRONT FORK LOWER LIGHT	Broken	25.00 FL	*25.00 FL
16	1		*FRONT NO PLATE	Bent	15.00 FS	*15.00 FS
17	1		*RIGHT HAND MIRROR	Broken	38.00 FL	*38.00 FL
18	1		*COOLANT TANK	Dented	285.00 FL	*250.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					1,918.00	1,688.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					190.30	167.30
Total Parts (\$\$)					1,727.70	1,520.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	45.00	45.00
2	LABOUR	New	350.00	300.00
Gross Labour Cost (S\$)			395.00	345.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >