



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200260

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 12/01/2022
Reference CC4/FCI21011031/Aga3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBL 3303U

Insured Veh. XD 2787U

Claim No. D21002995MFVS

Policy No. D-21097942MFVS

Accident Date 26/10/2021

Inspection Date 27/10/2021

Description	Total
Survey Inspection	646.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	
Less: Discount	-66.00
Subtotal	580.00
GST (7%)	40.60
Grand Total	620.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21011031/Aga3q2	
			Date: 12/01/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 2787U	Veh. Inspected	GBL 3303U	
Policy No.	D-21097942MFVS	Coverage (\$)	0.00	
Claim No.	D21002995MFVS	Excess (\$)	0.00	
Assign From	KAREN	Assign Date	27/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	VM20162093	Colour	WHITE	
Odometer	11227 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/80 R14	TOYO	6 mm	
L/H Front Tyre	165/80 R14	TOYO	6 mm	
R/H Rear Tyre	165/80 R14	TOYO	6 mm	
L/H Rear Tyre	165/80 R14	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/10/2021	Inspection Date	27/10/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 3303U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (N)	DEFORMED	695.90	695.90
1	REAR BUMPER O/S RETAINER (N)	NOT NECESSARY	86.60	-
1	REAR O/S TAIL LAMP (N)	CRACKED	364.60	364.60
1	REAR O/S TAIL LAMP INNER SEAL (N)	NECESSARY	20.00	20.00
1	REAR TAIL GATE (N)	DENTED	1,764.60	1,764.60
1	REAR TAIL GATE WEATHERSTRIP (N)	NOT NECESSARY	52.50	-
1	REAR O/S TAIL GATE SHOCK ABSORBER (N)	MISSING	310.60	310.60
1	REAR O/S TAIL GATE SHOCK ABSORBER BRACKET (N)	BENT	76.50	76.50
1	REAR TAIL GATE LOCK (N)	NOT NECESSARY	245.50	-
1	REAR O/S BODY PANEL (N)	DISTORTED	2,126.80	1,709.00
1	REAR O/S BODY PANEL INNER (N)	DISTORTED	1,760.20	1,637.00
1	REAR O/S BODY PANEL GLASS (N)	SHATTERED	628.50	628.50
1	REAR O/S BODY PANEL INNER BOARD (N)	DEFORMED	160.50	160.50
1	REAR O/S SLIDING DOOR (N)	DENTED	1,499.50	1,282.00
1	REAR O/S SLIDING DOOR GLASS (N)	CUT	665.60	665.60
1	REAR O/S SLIDING DOOR GUIDE HINGE (UPPER) (N)	NOT NECESSARY	95.00	-
1	REAR O/S SLIDING DOOR GUIDE HINGE (LOWER) (N)	NOT NECESSARY	95.00	-
1	REAR O/S SLIDING DOOR GUIDE HINGE (MIDDLE) (N)	NOT NECESSARY	110.00	-
1	REAR O/S SLIDING DOOR LOCK (REAR) (N)	NOT NECESSARY	201.00	-
1	REAR O/S SLIDING DOOR LOCK CATCH (REAR) (N)	NOT NECESSARY	88.00	-
1	REAR O/S SLIDING DOOR LOCK (FRONT) (N)	NOT NECESSARY	214.00	-
1	REAR O/S SLIDING DOOR LOCK CATCH (FRONT) (N)	NOT NECESSARY	85.00	-
1	REAR ROOF LINING (N)	CRUMPLED	1,325.60	1,325.60
1	REAR ROOF PANEL (N)	TO REPAIR SEE LABOUR	2,490.00	-
1	REAR O/S SLIDING DOOR GUIDE (N)	BENT	218.40	218.40
1	REAR O/S SLIDING DOOR GUIDE GARNISH (N)	MISSING	76.50	76.50
1	REAR O/S SLIDING DOOR GUIDE HANDLE (N)	CUT	233.10	233.10
1	FRONT O/S DRIVER DOOR (N)	DENTED	1,741.60	1,287.00
1	FRONT O/S FUEL LID (N)	DENTED	169.60	169.60
1	FRONT O/S SIDE MIRROR (N)	CRACKED	556.40	556.40

Report Ref No. CC4/FCI21011031/Aga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,815.71	-1,318.14
			16,341.39	11,863.26
	<u>SPECIAL NETT ITEMS</u>			
10	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR O/S STOPPER (SN)	NOT NECESSARY	65.40	-
1	REAR TAIL GATE 6 PAX EMBLEM (SN)	NECESSARY	15.00	15.00
1	REAR TAIL GATE 70 KMPH EMBLEM (SN)	NECESSARY	15.00	15.00
1	REAR TAIL GATE EMBLEM (SN)	NECESSARY	110.40	110.40
1	REAR TAIL GATE NV200 EMBLEM(SN)	NECESSARY	86.50	86.50
1	REAR TAIL GATE VANETTE EMBLEM (SN)	NECESSARY	75.40	75.40
1	REAR TAIL GATE STICKER (SN)	NECESSARY	150.00	150.00
1	REAR TAIL GATE WINDSCREEN MOULDING (SN)	NECESSARY	80.00	80.00
1	REAR TAIL GATE SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR 600KG STICKER (SN)	NECESSARY	8.00	8.00
1	REAR O/S BODY PANEL GLASS MOULDING (SN)	NECESSARY	80.00	80.00
1	REAR O/S BODY PANEL GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR O/S BODY PANEL GLASS SOLAR FILM (SN)	NECESSARY	150.00	150.00
8	REAR O/S BODY PANEL INNER BOARD CLIPS (SN)	NECESSARY	24.00	24.00
1	REAR O/S BODY PANEL STICKER (SN)	NECESSARY	200.00	200.00
1	REAR O/S SLIDING DOOR GLASS MOULDING (SN)	NECESSARY	80.00	80.00
1	REAR O/S SLIDING DOOR GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR O/S SLIDING DOOR GLASS SOLAR FILM (SN)	NECESSARY	150.00	100.00
1	FRONT O/S DRIVE DOOR STICKER (SN)	NECESSARY	250.00	250.00
1	FRONT O/S DRIVER DOOR COMPANY STICKER (SN)	NECESSARY	25.00	25.00
1	SET FRONT O/S DOOR GUARD PROTECTOR (SN)	NOT NECESSARY	120.00	-
			1,894.70	1,659.30
	<u>LABOUR</u>			
	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING.INCLUSIVE OF THE REPAIR OF REAR ROOF PANEL.		2,600.00	1,800.00
	TO SPRAY PAINTING.		1,800.00	1,400.00
	TO REMOVE AND REPLACE REAR O/S FENDER GLASS .		140.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE REAR O/S SLIDING DOOR GLASS .		140.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN .		150.00	120.00
	TO REMOVE AND REFIT REAR O/S SLIDING DOOR FITTINGS.		100.00	60.00
	TO REMOVE AND REFIT REAR O/S TAIL GATE FITTINGS.		100.00	80.00
	TO REMOVE AND REPLACE UPHOLSTERY TO FACILITATE REPAIR.		150.00	120.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR .		40.00	40.00
	TO CHECK WIRING.		100.00	30.00
	TO RESEAL ANTI RUST.		100.00	100.00
			5,420.00	3,870.00
GRAND TOTAL			23,656.09	17,392.56

RECOMMENDED COST OF REPAIRS				17,392.56
------------------------------------	--	--	--	------------------

Report Ref No. CC4/FCI21011031/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 3303U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 3303U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 3303U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

