

TP China.

Ashes.

SMG 2541B

Honda Vezel

RU11304631.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rear Bumper	Deformed	588.20	/
Rear Bumper Clips	new	30(SN)	/
Rear Bumper Side Holder	x 02	32 x 2 = 64	+
Rear Bumper Reflector	x 02	141.1 x 2 = 282.20	+
Rear Bumper Side Cover	x 02	195 x 2 = 390	+
Rear Bumper Side Cover Clips	new	30(SN)	+
Reverse Sensor	Damaged	280(SN) 200(SN)	
Rear End Panel	Repair	517	+
Rear End Panel Top Garnish		175.90	+
Rear End Panel Top Garnish Clips	new	20(SN)	+
Rear End Panel Sealant		60(SN)	+
Tailgate	Dented	1100	-
Tailgate lock	Damaged	184.60	/
Tailgate Weatherstripe	new	182.40	X

SMG2541B.

Tailgate Inner Trim Board	} ¹⁴ ₁₄	285.20	x
Tailgate Inner Trim Board Caps		30(SN)	x
Tailgate Glass Moulding	} ₁₄	111.20	/
Tailgate Glass Sealant		60(SN)	/
Velvet Wording	¹⁴	56.20	/
Rear Number Plate	} ₁₄	30(SN)	/
Rear Number Plate Holder		30(SN)	/

hist: 207000
 kmdo%: 1632.16
 S/N: 350
 Labour: 1240
 total: 3222.16.
 L/S: 2550
 04 days.

Panel Beating	1000	400	
Spray Painting	1000	400	
Wiring	50	30	
To remove reverse sensor	100	50	
To remove rear camera	100	50	
To remove upholstery	150	x	
To spray tuft coat	150	30	
To remove tailgate glass	180	120	
To transfer tailgate fittings	150	80	
To present vehicle at LTA authorized centre to resend wheel car plate			80. 100.