

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21011037/VTF3Q2
Date: 08/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100440190
Claimant Vehicle No :	SMT1484X	Insured Vehicle No :	SKX3366T
Date of Loss:	26/10/2021	Nature of Claim:	TP
		Claim No:	5165933428SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT1484X		
Make & Model:	HONDA ACCORD, 1.6 (M)	Engine No:	G4FGKH740403
Reg. Date:	30/03/2020 (Man. Year: 2019)	Chassis No:	KNAF3416ML5065743
Colour:	Grey	Odometer:	3326 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

11/8/21, 4:56 PM

Adjuster Report

Date of Assignment: 28/10/2021

Date Inspected: 28/10/2021 Inspected At:

Alpha Car Services Pte Ltd (HQ)
Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$59,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Cut	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER BRACKET	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	1		*REAR BUMPER BEAM	Cut	0.00 F	*- F
7	1		*REAR BUMPER DAMPER	Dented	0.00 F	*- F
8	1		*REVERSE SENSOR	Cut	0.00 F	*- F
9	1		*REAR END PANEL	Dented	0.00 F	*- F
10	1		*REAR END PANEL TOP GARNISH	Distorted	0.00 F	*- F
11	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
12	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
13	1		*BOOTLID	Dented	0.00 F	*- F
14	1		*BOOTLID MOULDING	Dented	0.00 F	*- F
15	1		*BOOTLID REFLECTOR	Cracked	0.00 F	*- F
16	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
17	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
18	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >