

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21011040/AQCE2

Date: 10/03/2022

REFERENCE

Insured/Claimant: YAP EWE JIN BENEDICT (YE YAOJUN)
Date of Loss: 23/10/2021

Policy No: 2100400488
Nature of Claim: OD Claim No: 1549402798SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR5186P**
Make & Model: AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A) Engine No: CZC218094
Reg. Date: 12/02/2015 (Man. Year: 2014) Chassis No: WAUZZZ8V6F1057644
Colour: Bronze Odometer: 51427 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$51,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,132.00	8,349.52	4,782.48	36.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,352.00	5,302.00	5,050.00	48.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,484.00	13,651.52	9,832.48	41.87
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	23,184.00	13,351.52	9,832.48	42.41
+ GST 7.00/7.00% (S\$)	1,622.88	934.61	688.27	42.41
Nett Amount (S\$)	24,806.88	14,286.13	10,520.75	42.41

INSPECTION

Date of Assignment: 28/10/2021

Date Inspected: 27/10/2021 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,233.00 FS	*1,786.40 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	2	*FRONT BUMPER COVER TRIM - LH / RH	Not Necessary	326.00 FS	*- FS
4	1	*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	163.00 FS	*- FS
5	4	*FRONT BUMPER PULL STRAP - LOWER	Not Necessary	206.00 FS	*- FS
6	2	*FRONT BUMPER GUIDE SECTION - LH / RH	Cracked	78.00 FS	*60.96 FS
7	1	*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	O/S Not Necessary/ N/S Missing	218.00 FS	*87.20 FS
8	1	*FRONT RADIATOR GRILLE	Cracked	691.00 FS	*552.40 FS
9	1	*FRONT RADIATOR GRILLE COVER	Not Necessary	98.00 FS	*- FS
10	1	*FRONT SIDE REINFORCEMENT	Dented	795.00 FS	*636.00 FS
11	1	*FRONT BUMPER FOAM FILLER PIECE	Cracked	137.00 FS	*109.60 FS
12	1	*FRONT REINFORCEMENT COVER	Cracked	56.00 FS	*44.48 FS
13	1	*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
14	1	*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
15	2	*HORN - LH / RH	Not Necessary	400.00 FS	*- FS
16	2	*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	338.00 FS	*- FS
17	2	*HEADLIGHT - LH / RH	Cracked	5,282.00 FS	*4,225.60 FS
18	2	*HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	386.00 FS	*- FS
19	1	*HEADLIGHT HOSE	Not Necessary	182.00 FS	*- FS
20	1	*FRONT RADIATOR AIR GUIDE - LH / RH	Deformed	50.00 FS	*38.88 FS
21	1	*FRONT RADIATOR AIR GUIDE - RH OUTER	Not Necessary	8.00 FS	*- FS
22	1	*FRONT RADIATOR AIR GUIDE - UPPER CENTER	Deformed	12.00 FS	*9.44 FS
23	1	*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
24	1	*SUNDRIES	Not Necessary	300.00 FS	*- FS
25	1	*FRONT LOCK CARRIER (Supplementary)	Cracked	727.00 FS	*581.60 FS
26	4	*COOLANT (Supplementary)	Necessary	95.00 FS	*75.52 FS
27	1	*BONNET CATCH HOOK (Supplementary)	Bent	63.00 FS	*50.32 FS
28	1	*OUTER TEMP. SENSOR BRACKET (Supplementary)	Damaged	19.00 FS	*14.56 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 13,132.00 8,349.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BITH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS	New	3,500.00	1,100.00
6	TO REMOVE AND REINSTALL AIRCON CONDENSER ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURE COOLING SYSTEM. TO CARRY OUT AIR CON VACUUM AND REGAS.	New	1,400.00	1,400.00
	(Supplementary)			
7	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	New	2,100.00	1,250.00
	(Supplementary)			
Gross Labour Cost (\$\$)			10,352.00	5,302.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >