

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC21011041/R1uce2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	15-12-2021 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SKX 9733C	Veh. Ir	spected	SG 5871H	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1147408-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	01/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MAN A95	c.c		10518	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	WMAA95ZZXG7003551	Coloui	ſ	MULTI COLOUR	
	Odometer	249337	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	275/70 R22.5	FIRENZ		8 mm	
	L/H Front Tyre	275/70 R22.5	FIRENZ	ZA	8 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	FIRENZ		8/8 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	FIRENZ	ZA	8/8 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/10/2021	Inspec	tion Date	01/11/2021	
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	ΓD		
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705					
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					